





DIV U

H-1



Suppression Repair Map EAST
 NORTH KLAMATHON INCIDENT
 OR-MED-268



- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed

North Klamathon
 Suppression Repair
 PNLYL8 (1502)
 OR-MED-268
 Sept. 30, 2018
 NAD83
 1:11,360