



Suppression Repair

Beachie Creek
ORWIF-200299
Riverside 7
10/05/20
Page: 7

- Repair Point Status**
- Repair Needed
 - Unknown
- Repair Line Status**
- Repair Needed
 - Unknown
- FC Point Type Repair Status Repair Comments Label**
- | | | | |
|---------------|---------------|--|--------|
| Drop Point | Repair Needed | | DP-111 |
| Repeater | Repair Needed | | CMD 8 |
| Value at Risk | Unknown | | |

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Chipper needed after fire-M. Debris on 10/19/2020. Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	
Road as Completed Line	Repair Needed	Chipping needed to clear ditches	11645
Planned Fire Line	Unknown		464
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17307
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17307
Other	Unknown		257
Other	Unknown		479
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598
Other	Unknown		813
Other	Unknown		827
Other	Unknown		1312
Access or Improved Road	Unknown		29
Access or Improved Road	Unknown		155
Access or Improved Road	Unknown		341
Access or Improved Road	Unknown		479
Access or Improved Road	Unknown		576
Access or Improved Road	Unknown		601
Access or Improved Road	Unknown		942
Access or Improved Road	Unknown		2043
Access or Improved Road	Unknown		6158
Access or Improved Road	Unknown		8554



1:33,000 - 10/4/2020 2209
Acres from GIS
North American 1983 Datum, LatLong Grid

