

Suppression Repair

Beachie Creek
ORWIF-200299
Riverside 3
10/06/20
Page: 3


- Repair Point Status**
- Repair Needed
 - No Repair Needed
 - Unknown
- Repair Line Status**
- Completed - Ready for Inspection
 - Repair Needed
 - Unknown
- Legend**
- X Division Break
 - ▬ Contained Line
 - ▬ Completed Dozer Line
 - ▬ Completed Hand Line
 - ▬ Road as Completed Line
 - ▬ Access or Improved Road
 - ▬ Line Break Completed
 - ▬ Aerial Hazard
 - ▬ Uncontrolled Fire Edge
 - ▬ Wildfire Daily Fire Perimeter
 - ▬ Structures
 - ▬ Fire Station
 - ▬ Repeater
 - ▬ Water Source
 - ▬ Intermediate road
 - ▬ Minor road
 - ▬ Decommissioned or Closed
 - ▬ Rivers and Streams
 - ▬ Lake, Pond or Reservoir
 - ▬ County Boundary
 - ▬ Ranger District Boundaries
 - ▬ Forest Service Wilderness Area
 - ▬ Bureau of Land Management
 - ▬ U.S. Forest Service
 - ▬ State
 - ▬ Local Government
 - ▬ Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Bridge	Repair Needed		Bridge Out
Bridge	Repair Needed		
Dozer Push	Repair Needed		
Dozer Push	Repair Needed		
Drop Point	No Repair Needed	Road turnout, no repair needed. REAF BERNARDS	DP-11
Drop Point	No Repair Needed		DP-12
Drop Point	No Repair Needed	No repairs, REAF BERNARDS	DP-13
Drop Point	Repair Needed		DP-10
Drop Point	Repair Needed		DP-15
Drop Point	Repair Needed		DP-2
Drop Point	Repair Needed		DP-30
Drop Point	Repair Needed		DP-4
Drop Point	Repair Needed		DP-6
Drop Point	Repair Needed		DP-7
Drop Point	Repair Needed		DP-80
Drop Point	Repair Needed		DP-83
Drop Point	Repair Needed		DP-83

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	Repair Needed		DP-84
Drop Point	Repair Needed		DP-86
Drop Point	Repair Needed		DP-89
Drop Point	Repair Needed		DP-9
Drop Point	Repair Needed		DP-94
Drop Point	Repair Needed		DP-95
Drop Point	Repair Needed		DP-96
Drop Point	Repair Needed		DP-97
Drop Point	Repair Needed		DP-98
Drop Point	Repair Needed		DP-99
Repeater	Repair Needed		CHD 9
Water Source	Repair Needed		
Water Source	Repair Needed		
Water Source	Repair Needed		
Water Source	Unknown		

FC Line Type	Repair Status	Repair Comments	Length Feet
Unknown	Unknown		120
Road as Completed Line	Unknown		194
Road as Completed Line	Unknown		215
Road as Completed Line	Unknown		245
Road as Completed Line	Unknown		298
Road as Completed Line	Unknown		303
Road as Completed Line	Unknown		402
Road as Completed Line	Unknown		493
Road as Completed Line	Unknown		519
Road as Completed Line	Unknown		582
Road as Completed Line	Unknown		705
Road as Completed Line	Unknown		707
Road as Completed Line	Unknown		729
Road as Completed Line	Unknown		747
Road as Completed Line	Unknown		808
Road as Completed Line	Unknown		851
Road as Completed Line	Unknown		851
Road as Completed Line	Unknown		1048
Road as Completed Line	Unknown		1110
Road as Completed Line	Unknown		1244
Road as Completed Line	Unknown		1208
Road as Completed Line	Unknown		1469
Road as Completed Line	Unknown		1495
Road as Completed Line	Unknown		1862
Road as Completed Line	Unknown		1929
Road as Completed Line	Unknown		2072
Road as Completed Line	Unknown		2266
Road as Completed Line	Unknown		2563
Road as Completed Line	Unknown		2380
Road as Completed Line	Unknown		2573
Road as Completed Line	Unknown		6005
Road as Completed Line	Unknown		28087
Road as Completed Line	Repair Needed	pull berms, waterbars, block abv access	1180
Road as Completed Line	Repair Needed	waterbar	1372
Road as Completed Line	Repair Needed		2059
Road as Completed Line	Repair Needed		2761
Road as Completed Line	Repair Needed		2903
Road as Completed Line	Repair Needed		3122
Road as Completed Line	Repair Needed	chip wind row of slash on green side of road	3262
Proposed Dozer Line	Unknown		9306
Line Break Completed	Repair Needed		343
Completed Hand Line	Unknown		185
Completed Hand Line	Unknown		311
Completed Hand Line	Unknown		607
Completed Hand Line	Unknown		712
Completed Hand Line	Unknown		901
Completed Hand Line	Unknown		925
Completed Hand Line	Unknown		1040
Completed Hand Line	Unknown		1156
Completed Hand Line	Unknown		1264
Completed Hand Line	Unknown		1460
Completed Hand Line	Unknown		1609
Completed Hand Line	Unknown		2096
Completed Hand Line	Unknown		2294
Completed Hand Line	Unknown		2476
Completed Hand Line	Unknown		2782
Completed Hand Line	Unknown		2946
Completed Hand Line	Unknown		3243
Completed Hand Line	Unknown		3975
Completed Hand Line	Repair Needed	minimal waterbars needed on steep portions near bottom	358
Completed Hand Line	Repair Needed		596
Completed Hand Line	Repair Needed		602
Completed Hand Line	Repair Needed	pull berms, waterbars, scatter slash, block abv access	662
Completed Hand Line	Repair Needed		668
Completed Hand Line	Repair Needed	pull berms, waterbars, scatter slash, block abv access	691
Completed Hand Line	Repair Needed		1026
Completed Hand Line	Repair Needed	Line is a mix of one line/trail and handline w/ cut trenches. Will need repair. TRICK Muttie	1186

FC Line Type	Repair Status	Repair Comments	Length Feet
Completed Hand Line	Repair Needed	A mix of existing trail, hand line, and cold trail.	1301
Completed Hand Line	Repair Needed		2777
Completed Hand Line	Repair Needed		2923
Completed Hand Line	Repair Needed		3337
Completed Dozer Line	Unknown		128
Completed Dozer Line	Unknown		134
Completed Dozer Line	Unknown		380
Completed Dozer Line	Unknown		403
Completed Dozer Line	Unknown		408
Completed Dozer Line	Unknown		434
Completed Dozer Line	Unknown		453
Completed Dozer Line	Unknown		459
Completed Dozer Line	Unknown	Only 100' of dozer line on west end. The rest is just brushed out by hand.	520
Completed Dozer Line	Unknown		520
Completed Dozer Line	Unknown		520
Completed Dozer Line	Unknown		533
Completed Dozer Line	Unknown		546
Completed Dozer Line	Unknown		593
Completed Dozer Line	Unknown		602
Completed Dozer Line	Unknown		602
Completed Dozer Line	Unknown		619
Completed Dozer Line	Unknown		631
Completed Dozer Line	Unknown		635
Completed Dozer Line	Unknown		646
Completed Dozer Line	Unknown		654
Completed Dozer Line	Unknown		714
Completed Dozer Line	Unknown		761
Completed Dozer Line	Unknown		825
Completed Dozer Line	Unknown		862
Completed Dozer Line	Unknown		865
Completed Dozer Line	Unknown		955
Completed Dozer Line	Unknown		965
Completed Dozer Line	Unknown		1016
Completed Dozer Line	Unknown		1052
Completed Dozer Line	Unknown		1071
Completed Dozer Line	Unknown		1137
Completed Dozer Line	Unknown		1153
Completed Dozer Line	Unknown		1180
Completed Dozer Line	Unknown		1209
Completed Dozer Line	Unknown		1225
Completed Dozer Line	Unknown		1239
Completed Dozer Line	Unknown		1535
Completed Dozer Line	Unknown		1668
Completed Dozer Line	Unknown		1750
Completed Dozer Line	Unknown		1766
Completed Dozer Line	Unknown		1980
Completed Dozer Line	Unknown		1992
Completed Dozer Line	Unknown		2015
Completed Dozer Line	Unknown		2030
Completed Dozer Line	Unknown		2039
Completed Dozer Line	Unknown	non inc. Personnel installed	2194
Completed Dozer Line	Unknown		2460
Completed Dozer Line	Unknown		2443
Completed Dozer Line	Unknown		2544
Completed Dozer Line	Unknown		2907
Completed Dozer Line	Unknown		2993
Completed Dozer Line	Unknown		3243
Completed Dozer Line	Unknown		3812
Completed Dozer Line	Unknown		4676
Completed Dozer Line	Unknown		4741
Completed Dozer Line	Unknown		6100
Completed Dozer Line	Unknown		7532
Completed Dozer Line	Unknown		8018
Completed Dozer Line	Unknown		10943
Completed Dozer Line	Repair Needed	standard suppression repair for Redland land	78
Completed Dozer Line	Repair Needed		100
Completed Dozer Line	Repair Needed	Access needs blocked	335
Completed Dozer Line	Repair Needed	pull berms, waterbars, scatter slash, block abv access	394
Completed Dozer Line	Repair Needed		471
Completed Dozer Line	Repair Needed	pull berms, waterbars, scatter slash, block abv access	633
Completed Dozer Line	Repair Needed		775



0 0.5 1 2 Miles

1:33,000 - 10/5/2020 2213
Acres from GIS
North American 1983 Datum, LatLong Grid