

# Suppression Repair


Beachie Creek  
ORWIF-200299  
Riverside  
ORMHF-000859  
10/09/20  
Page: 5

- BPA Transmission Lines
- Minor road
- Decommissioned or Closed
- ▲ Structures
- ▲ Campground
- ▲ Trailhead
- ▲ State Highway
- ▲ Major road
- ▲ Intermediate road
- County Boundary
- Ranger District Boundaries
- Forest Service Wilderness Area
- U.S. Forest Service
- Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Dozer Push	Repair Needed	18 inch thick slash lightly scattered from where soil is exposed. -Lin kyan	4611-8
Dozer Push	Repair Needed	18 inch thick slash lightly scattered slash on top of exposed soil. In kyan 10-3-20	4611-9
Drop Point	Completed - Inspected		4611-12
Drop Point	No Repair Needed		4611-13
Drop Point	No Repair Needed		
Drop Point	No Repair Needed		
Drop Point	No Repair Needed		
Drop Point	No Repair Needed		
Drop Point	Repair Needed	18 inch thick slash lightly scattered on the exposed soil at turn around across (south from log deck. -Lin kyan 10-3-20)	
Landing or Log Deck			4611-10
Landing or Log Deck			4611-14
Landing or Log Deck			4611-15
Landing or Log Deck			4611-16
Landing or Log Deck			4611-17
Landing or Log Deck			4611-18
Landing or Log Deck			4611-19
Landing or Log Deck			4611-20
Landing or Log Deck			4611-21
Landing or Log Deck			4611-22

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Significant mch. Slash piles will need to be disposed of. Flush cut purges and stumps where needed. Chipping needed.	
Road as Completed Line	Repair Needed	Chipper needed after fire-M. DeAngelo Sep 15, 2020. Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	
Road as Completed Line	Repair Needed	Light chipping needed	420
Road as Completed Line	In Progress	Chipping needed	20496
Road as Completed Line	Completed - Inspected	Sweeping of debris and light chipping need at intersection of DP 102	
Road as Completed Line	Completed - Inspected	Sweeping of debris	1440
Road as Completed Line	Completed - Inspected	Chipping needed to clear ditches	11641
Road as Completed Line	Completed - Inspected	Chipping needed north of Shellrock Campground	13308
Planned Fire Line	Unknown		464
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17307
Planned Fire Line	Repair Needed	Chipping needed	20841
Planned Fire Line	In Progress	Chipping needed	20835
Planned Fire Line	In Progress	Road grading, remove berms, repair cut and fill slopes (marked separately), and chipping -Sung, Robert Sanders; stumps, slash, berm and grading underway 10/7/20. Div o-o says done by 10/9	24812
Planned Fire Line	Completed - Inspected	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17301
Planned Fire Line	Completed - Inspected	Chipping needed throughout NF 58 and entry to NF 5830 and NF 150. Crews needed to sweep debris.	40140
Other	Unknown		257
Other	Unknown		479
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598

FC Line Type	Repair Status	Repair Comments	Length Feet
Other	Unknown		813
Other	Unknown		827
Other	Unknown		1312
Line Break Completed	Unknown		3160
Line Break Completed	Unknown		4331
Line Break Completed	Repair Needed	Logs in ditch need to be removed. Chip smaller material. Berms need to be knocked down. Rocky debris behind shoulder needs additional repair	2083
Line Break Completed	Completed - Inspected	Light chipping and sweeping needed	1139
Completed Dozer Line	Repair Needed	Pull in berms, may not be needed until log deck is removed	194
Completed Dozer Line	Repair Needed	Robert Sanders: the road edge is chewed up from machines and parking, speed, and/or slash. same treatment around log deck	506
Access or Improved Road	Unknown		29
Access or Improved Road	Unknown		155
Access or Improved Road	Unknown		341
Access or Improved Road	Unknown		479
Access or Improved Road	Unknown		576
Access or Improved Road	Unknown		601
Access or Improved Road	Unknown		842
Access or Improved Road	Unknown		2043
Access or Improved Road	Unknown		2241
Access or Improved Road	Unknown		6150
Access or Improved Road	Unknown		8554
Access or Improved Road	Unknown		20630



1:33,000 - 10/8/2021 2122  
Acres from GIS  
North American 1983 Datum, LatLong Grid

