

Suppression Repair

Beachie Creek
ORWIF-200299
Riverside
ORMHF-000859
10/08/20
Page: 8

- | | | | |
|---|---|---|--|
| <ul style="list-style-type: none"> Repair Point Status Repair Needed No Repair Needed Unknown | <ul style="list-style-type: none"> Drop Site Drop Point Fire Station Gate Internet Access Mobile Weather Unit Repeater Stream Crossing Water Source Water Development or Draft Site Zone Break Division Break Bridge Camp Closure Culvert | <ul style="list-style-type: none"> Road as Completed Line Access or Improved Road Line Break Completed Planned Fire Line Planned Secondary Line Aerial Hazard Uncontrolled Fire Edge BPA Transmission Lines Wildfire Daily Fire Perimeter Structures Fire Station City, Town, or Community State Highway | <ul style="list-style-type: none"> County Road Major road Intermediate road Minor road Decommissioned or Closed Rivers and Streams Lake, Pond or Reservoir County Boundary City Limits Bureau of Land Management State Local Government Private/Unknown |
|---|---|---|--|

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	No Repair Needed		DP-36
Drop Point	Unknown		DP-38
Drop Point	Unknown		DP-40
Drop Point	Unknown		DP-43
Drop Point	Unknown		DP-46
Drop Point	Unknown		DP-47
Drop Point	Unknown		DP-83
Drop Point	Unknown		DP-84
Drop Point	Unknown		DP-86
Drop Point	Unknown		DP-87
Drop Point	Unknown		DP-18
Drop Point	Unknown		DP-20
Drop Point	Unknown		DP-21
Drop Point	Unknown		DP-22
Drop Point	Unknown		DP-23
Drop Point	Unknown		DP-24
Drop Point	Unknown		DP-31
Drop Point	Unknown		DP-33
Drop Point	Unknown		DP-35

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	Unknown		DP-36
Drop Point	Unknown		DP-38
Drop Point	Unknown		DP-40
Drop Point	Unknown		DP-43
Drop Point	Unknown		DP-46
Drop Point	Unknown		DP-47
Drop Point	Unknown		DP-83
Drop Point	Unknown		DP-84
Drop Point	Unknown		DP-86
Drop Point	Unknown		DP-87
Drop Point	Unknown		DP-18
Drop Point	Unknown		DP-20
Drop Point	Unknown		DP-21
Drop Point	Unknown		DP-22
Drop Point	Unknown		DP-23
Drop Point	Unknown		DP-24
Drop Point	Unknown		DP-31
Drop Point	Unknown		DP-33
Drop Point	Unknown		DP-35

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown	Consult local land owner	454
Road as Completed Line	Unknown	Consult READS	950
Road as Completed Line	Unknown		996
Road as Completed Line	Unknown	Consult bandowner, line width varies 10-30, site of pushed over trees	1507
Road as Completed Line	Unknown		1770
Road as Completed Line	Unknown		1905
Road as Completed Line	Unknown		3911
Road as Completed Line	Unknown	Repair for local unit specs-BLM	1915
Road as Completed Line	Unknown		1528
Road as Completed Line	Unknown		1953
Road as Completed Line	Unknown		2091
Road as Completed Line	Unknown		2040
Road as Completed Line	Unknown	Consult local land owner	2656
Road as Completed Line	Unknown	A little prep needed before burning	12115
Road as Completed Line	Repair Needed	We see no need for repair here. This appears to be good road. Jake Goebel E-279 on 10/6.	2094
Road as Completed Line	Repair Needed	Open drainage through side cast material on downhill side of the road.	7864
Road as Completed Line	Other - See Comments	Consult local land owner	1730
Road as Completed Line	Other - See Comments	consult landowner	3581
Road as Completed Line	Completed - Ready for Inspection	Ditch is filled with debris, but it appears water is still draining.	7864
Road as Completed Line	Completed - Ready for Inspection	Ditch is filled with debris, but it looks like the road is still draining.	7864
Road as Completed Line	Completed - Ready for Inspection		7864
Road as Completed Line	Unknown	Consult landowner	3738
Planned Secondary Line	Other - See Comments	Difficult to back fire off the river or road. Heliborch is suggested method. Road is in excellent condition, paved and accessible by any vehicle. Good ingress and egress.	27113
Other	Unknown		751
Other	Unknown		1065
Completed Hand Line	Unknown		375
Completed Hand Line	Unknown		476
Completed Hand Line	Unknown		505
Completed Hand Line	Unknown		539
Completed Hand Line	Unknown		669
Completed Hand Line	Unknown		946
Completed Hand Line	Unknown		1086
Completed Hand Line	Unknown		1803
Completed Hand Line	Unknown		4955
Completed Hand Line	Repair Needed	obliterate berms, scatter slash over line	
Completed Hand Line	Repair Needed	obliterate berm, scatter slash over line	
Completed Hand Line	Completed - Ready for Inspection		1463
Completed Hand Line	Completed - Ready for Inspection	I pulled the flagging used to mark the trail. I left two pieces to mark the beginning of the trail.	7864
Completed Hand Line	Completed - Inspected	Hand line has been rehabbed water bared and covered with debris.	1142
Completed Dozer Line	Unknown	medium excavator with grapple bucket	
Completed Dozer Line	Unknown		457
Completed Dozer Line	Unknown	Consult local land owner; has berm from dozer push, some pushed over trees	961

FC Line Type	Repair Status	Repair Comments	Length Feet
Completed Dozer Line	Unknown		967
Completed Dozer Line	Unknown		1177
Completed Dozer Line	Unknown		1351
Completed Dozer Line	Unknown		1385
Completed Dozer Line	Unknown		1641
Completed Dozer Line	Unknown		3315
Completed Dozer Line	Unknown		3738
Completed Dozer Line	Unknown		3802
Completed Dozer Line	Unknown		4635
Completed Dozer Line	Unknown		4955
Completed Dozer Line	Repair Needed	handrow obliterate berms scatter slash back on line	
Completed Dozer Line	Repair Needed	obliterate berms scatter slash back overline	
Completed Dozer Line	Repair Needed	handrow repair obliterate berms scatter slash back over line	
Completed Dozer Line	Repair Needed	Berms obliterated, slash scattered, minimal trail repair	
Completed Dozer Line	Repair Needed	Light to medium excavator with grapple bucket	
Completed Dozer Line	Repair Needed	Light to medium excavator, remove berms and scatter slash	
Completed Dozer Line	Repair Needed	Excavator needed, obliterate berms and scatter slash water bars as per repair plan. Water bar on dozer line just above trail. "Stop down drain" constructed of rock across trail where water bar drains. Retaining curb constructed of rock on lower side of trail adjacent to dozer intersection. Scatter slash heavily across beginning of dozer line above trail.	
Completed Dozer Line	Repair Needed	Repair per local BLM specs, obliterate berms and slash piles, water bar as needed, needs medium excavator with grapple claw, access through private land to south	
Completed Dozer Line	Repair Needed	consult landowner, likely needs medium excavator	
Completed Dozer Line	Repair Needed	consult landowner, need medium excavator with grapple bucket	
Completed Dozer Line	Repair Needed	Dozer line no water bars. Only a few water bars needed on one slope to be up to spec.	
Completed Dozer Line	Repair Needed		1400
Completed Dozer Line	Repair Needed	Repair per local specs, needs a few water bars on slopes, obliterate berms and slash piles, scatter slash on line. Consult local landowner for line off BLM land. Note: Dozer line on private ground is okay as is. No repair required. However the fence line is out and will need repaired at the BLM/private property line. Jake Goebel E-279	3470
Completed Dozer Line	Repair Needed	May have been constructed by local volunteers	3738
Completed Dozer Line	Repair Needed	Recently harvested area.	7864
Completed Dozer Line	Repair Needed		7864
Completed Dozer Line	Other - See Comments	Portions of this route may have been existing ATV trail. Consult land owner.	3738
Completed Dozer Line	Completed - Ready for Inspection	Hand crew repaired	7864
Completed Dozer Line	Completed - Ready for Inspection		7864
Completed Dozer Line	Completed - Inspected	Completed dozer line with water bars no more repair needed.	
Completed Dozer Line	Completed - Inspected	Flat dozer line. No repair needed.	
Completed Dozer Line	Completed - Inspected	Adequate water bars completed.	
Completed Dozer Line	Completed - Inspected		12347
Completed Dozer Line	Completed - Inspected	consult land owner	

