

Suppression Repair

Beachie Creek
 ORWIF-200299
Riverside 5
 Riverside
 ORMHF-000859
 10/10/20
 Page: 5

- BPA Transmission Lines
- Minor road
- Decommissioned or Closed
- County Boundary
- Ranger District Boundaries
- Forest Service Wilderness Area
- U.S. Forest Service
- Private/Unknown
- ▲ Structures
- ▲ Campground
- ▲ Trailhead
- State Highway
- Major road
- Intermediate road

FC Point Type	Repair Status	Repair Comments	Label
Dozer Push	Repair Needed	18 inch thick slash lightly scattered from where soil is exposed. -Lin kyan	4611-8
Dozer Push	Repair Needed	18 inch thick slash lightly scattered slash on top of exposed soil. In kyan 10-3-20	4611-9
Drop Point	Completed - Inspected		DP-101
Drop Point	No Repair Needed		DP-100
Drop Point	No Repair Needed		DP-102
Drop Point	No Repair Needed		DP-106
Drop Point	No Repair Needed		DP-110
Drop Point	No Repair Needed		DP-111
Drop Point	No Repair Needed		DP-112
Drop Point	No Repair Needed		DP-65
Drop Point	Repair Needed		DP-114
Landing or Log Deck			4611-10
Landing or Log Deck			4611-14
Landing or Log Deck			4611-15
Landing or Log Deck			4611-16
Landing or Log Deck			4611-17
Landing or Log Deck			4611-18
Landing or Log Deck			4611-19
Landing or Log Deck			4611-20
Landing or Log Deck			4611-4
Landing or Log Deck			4611-5
Landing or Log Deck			4611-6/7
Landing or Log Deck			4611-13
Landing or Log Deck			4611-14
Landing or Log Deck			4611-15
Landing or Log Deck			4611-16
Landing or Log Deck			4611-17
Landing or Log Deck			4611-18
Landing or Log Deck			4611-19
Landing or Log Deck			4611-20
Landing or Log Deck			4611-4
Landing or Log Deck			4611-5
Landing or Log Deck			4611-6/7

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Significant morch. Slash piles will need to be disposed of. Flush cut purges and stumps where needed. Chipping needed.	827
Road as Completed Line	Repair Needed	Chipper needed after fire-M. DuRango Sep 15, 2020. Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	1312
Road as Completed Line	Repair Needed	Light chipping needed	3160
Road as Completed Line	In Progress	Chipping needed	4331
Road as Completed Line	Completed - Inspected	Sweeping of debris and light chipping need at intersection of DP 102	2083
Road as Completed Line	Completed - Inspected	Sweeping of debris	1139
Road as Completed Line	Completed - Inspected	Chipping needed north of Shellrock Campground	194
Road as Completed Line	Completed - Inspected	Chipping needed	506
Road as Completed Line	Completed - Inspected	Chipping needed north of Shellrock Campground	29
Planned Fire Line	Unknown		155
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	341
Planned Fire Line	Repair Needed	Chipping needed	479
Planned Fire Line	In Progress	Road grading, remove berms, repair cut and fill slopes (marked separately), and chipping -Sung, Robert Sanders; stumps, slash, berm and grading underway 10/7/20. Div o-o says done by 10/9	576
Planned Fire Line	Completed - Inspected	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	601
Planned Fire Line	Completed - Inspected	Chipping needed throughout NF 58 and entry to NF 5830 and NF 150. Crews needed to sweep debris.	842
Other	Unknown		2043
Other	Unknown		2241
Other	Unknown		6150
Other	Unknown		8554
Other	Unknown		20630
Other	Unknown		257
Other	Unknown		479
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598

0 0.5 1 2 Miles

1:33,000 - 10/9/2020 2221
 Acres from GIS
 North American 1983 Datum, LatLong Grid

