

Repair Points - High Priority

FeatureStatus = 'Approved'
 DeleteThis NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')
 RepairPriority = High

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
152	Other	Needs Assessment		
43	Drop Point	Repair Needed		
93	Drop Point	Repair Needed		
160	Dozer Push	Repair Needed	Full repair	Pull in berms, seed and straw. cleared for arch by Slaton 8.2.23
4	Helispot	Completed - Inspected		
60	Drop Point	Repair Needed		remove flagging, no other repairs needed. BM 8/22
177	Repair Point	Repair Needed	Light Repair Meadow Repair	Seed. No straw. Danthonia californica and/or Elymus glaucus
182	Water Development or Draft Site	Repair Needed		
189	Other	Needs Assessment		
190	Repair Point	Repair Needed	Full repair	Seed, straw, block entrances, cover in veg (REAF Johannsen)100x200 ft BM8/22
194	Repair Point	Repair Needed	Re-establish ditch line on gravel portion of road to culvert at junction with dirt Spur. REAF JRH 7/28	Ditch line filled in, water running down gravel road and dumping onto dirt Spur. Direct water to culvert REAF JRH 7/28
29	Drop Point	Repair Needed		
27	Drop Point	Repair Needed		no repair needed BM 8/22
202	Repair Point	Repair Needed	Pull in berms, scatter veg, seed and straw 75x50ft BM 8/22	Pull in berms, scatter slash, seed and straw
204	Repair Point	Repair Needed	Yes	Seed with Elymus glaucus BIRD 7/25
205	Resource Location	Repair Needed	Repair Light	Pull in equipment ruts and bring to grade for erosion control.
208	Repair Point	Repair Needed	Yes	End of complete repair section. Check with Tbird - working on plan with Ptarmagin trails (forest partner)
209	Repair Point	Repair Needed	Yes	Replace boulders to block this area from OHV.
211	Repair Point	Repair Needed	Yes	Hide the line from the road and block entrance with tank trap type thing to prevent OHV use
34	Drop Point	Repair Needed		
282	Repair Point	Repair Needed	Block and water bar. REAF JRH 7/27	Repair Dozer line. REAF JRH 7/27
285	Landing or Log Deck	Repair Needed	Full repair	Log deck 4-6 loads botany cleared AB 7.26 Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26
130	Drop Point	Repair Needed		
96	Drop Point	Repair Needed		
301	Culvert	Repair Needed	Clean out inlet	
302	Culvert	Repair Needed	Clean out inlet	
333	Repair Point	Repair Needed	Repair Light. Block, waterbar and slash. REAF JRH 7/28	Old road prism/dozer line opened. REAF JRH 7/28
339	Landing or Log Deck	Repair Needed	Full repair	French broom growing across on 1503, pulled, but seed source could be present in landing. seed and mulch once logs are moved. REAF Martin 8/26
344	Resource Location	Repair Needed		handwork only, MIST Tactics, pull flagging
345	Landing or Log Deck	Repair Needed	Full repair	Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26
354	Repair Point	Repair Needed		Everything NW towards 1503 merch timber. Needs to be processed and self loader. Slash chipped after processing. AB 7.31
402	Repair Point	Repair Needed	Full repair	Quarry was infested with invasive cheat grass and dozed to create a parking area. Seed and straw 200x30ft. Monitor for spread post fire. Grade to prevent ponding of water on quarry floor
413	Repair Point	Repair Needed	remove when no longer needed	photos in ESA box folder
519	Bridge	Repair Needed	remove when no longer needed	
593	Repair Point	Repair Needed		
594	Dozer Push	Repair Needed		pull in berms, scatter slash, seed. ingasives present BM 8/23
613	Stream Crossing	Repair Needed	full repair stream crossing	coconut matting to maintain stability of steep drainage crossing. REAF Calvin 8/25 Div T approved to change status
617	Stream Crossing	Repair Needed	full repair, stream crossing	stabilize dozer line leading to stream with coconut matting. READ present during repair. REAF EL 8/25 DIV T approved to change status
615	Stream Crossing	Repair Needed	full repair, stream crossing	stabilize dozer line leading to stream with coconut matting. read present during repair. REAF EL 8/25 DIV T approved to change status.
	Culvert	Repair Needed	Full repair	READ Sargent 8/26/23. Dig out inlet with excavator. Culvert blocked by debris from suppression activity
411	Landing or Log Deck	Repair Needed	Full repair	Log decks and slash piles from contingency line. REAF AG 08/2/23Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26
412	Landing or Log Deck	Repair Needed	Light repair	Re-using existing landing for log decks and slash piles. REAF AG 8/2/2023 Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26