

Repair Points - Priority Unknown

Point Type NOT IN ('Repair Point', 'Road Repair')
 FeatureStatus = 'Approved'
 DeleteThis NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')
 RepairPriority = High

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
150	Fire Origin	Repair Needed		
45	Drop Point	Repair Needed		no repair needed BM 8/22
1	Helispot	Repair Needed		
163	Value at Risk	Needs Assessment	No repair needed	N/A
2	Helispot	Repair Needed	None	Monitor for invasive cheatgrass post fire
91	Drop Point	Repair Needed		
165	Dip Site	Repair Needed	Remove bleach and trash, remove fish screen and return to READS/GB Ranger Station	
44	Drop Point	Repair Needed		seed all ground disturbance 40x10 ft, invasives present in area BM 8/23
166	Value at Risk	Needs Assessment	None	High priority invasive weeds site. Monitor for spread post fire
5	Helispot	Repair Needed	remove flagging	
6	Helispot	Repair Needed		
168	Other	Needs Assessment		
80	Drop Point	Repair Needed		
105	Drop Point	Repair Needed		
116	Drop Point	Needs Assessment		
101	Drop Point	Repair Needed		
61	Drop Point	Repair Needed		
170	Repeater	Repair Needed		
171	Dozer Push	Repair Needed	Full repair	Pull in berm, cover in slash, seed
172	Dozer Push	Repair Needed	Full repair	Pull in berms, scatter slash, seed
173	Dozer Push	Repair Needed	Full repair	Pull in berms, scatter slash, seed
178	Value at Risk	Needs Assessment	needs to be rung with line	
179	Camp	Repair Needed	Full repair	see repair plan for specific instructions.
180	Camp	Repair Needed	Repair Needed	
24	Drop Point	Repair Needed		
186	Resource Location	Needs Assessment		
187	Resource Location	Needs Assessment		
64	Drop Point	Repair Needed		
62	Drop Point	Repair Needed	pile material to disguise entrance	
191	Repeater	Repair Needed		
192	Repeater	Repair Needed		
193	Repeater	Repair Needed		
197	Resource Location	Needs Assessment	Yes	Remove flagging
199	Resource Location	Needs Assessment		
201	Water Source	Repair Needed		
25	Drop Point	Repair Needed		no repair needed BM 8/22
101	Helispot	Repair Needed		
203	Resource Location	Needs Assessment		Collect flagging
206	Value at Risk	Needs Assessment		
207	Water Source	Repair Needed		return fish screens to district after ops done. REAF Jackson 7/26/23
30	Drop Point	Repair Needed		
212	Dip Site	Repair Needed		
213	Dip Site	Repair Needed		
214	Dip Site	Repair Needed		
10	Helispot	Completed - Inspected		
215	Safety Zone	Repair Needed		
234	Water Development or Draft Site	Repair Needed		return fish screen to district after ops done. REAF Jackson 7/26/23
609	Helispot	Repair Needed		Pull back berms, block entrance from road, seed. 60x100ft, mature Phacelia seed nearby could pick and spread. See if local district wants to keep helicopter for future use. BM 8/22
14	Helispot	Repair Needed		
251	Water Source	Repair Needed	No	
252	Restricted Water Source	Needs Assessment	No	
284	Resource Location	Completed - Inspected		
92	Drop Point	Repair Needed		
97	Drop Point	Repair Needed		
18	Helispot	Repair Needed		
329	Other	Needs Assessment		
331	Mobile Weather Unit	Completed - Inspected		
22	Helispot	Repair Needed		
24	Helispot	Repair Needed		
338	Resource Location	Needs Assessment		
341	Repeater	Repair Needed		
343	Other	Needs Assessment		Minor prep completed. No repair necessary
30	Helispot	Completed - Inspected		
32	Helispot	Repair Needed		
346	Hazard	Needs Assessment		
348	Resource Location	Repair Needed		

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
352	Dozer Push	Repair Needed	Full repair	Pull in berms, cover in slash, seed 60x10 ft (SIJ 07-30) Arch LL 8/24
353	Dip Site	Repair Needed		
356	Resource Location	Repair Needed		pull flagging
357	Resource Location	Needs Assessment		
393	Dozer Push	Repair Needed	Full Repair	Pull back berm, seed, cover with slash. (20230801 - K. Carlson). Berm pulled back (20230828 - J.Sciarrino).
394	Repeater	Repair Needed		
395	Repeater	Repair Needed		
396	Resource Location	Repair Needed		pull flagging
399	Landing or Log Deck	Needs Assessment		
401	Landing or Log Deck	Needs Assessment		
405	Water Source	Repair Needed	None	
63	Drop Point	Repair Needed		
414	Dozer Push	Repair Needed	Full Repair	Bring to grade with drainage slope, seed, and monitor for Cheat Grass. 08/03 -REAF KC
415	Dozer Push	Repair Needed	Full Repair	Bring to grade with drainage slope, seed, and monitor for Cheat Grass. 08/03 -REAF KC
416	Dozer Push	Repair Needed		
417	Dozer Push	Needs Assessment	Full Repair	Pull in berm, bring to grade, cover with slash as available. 08/03-REAF KC
418	Dozer Push	Needs Assessment	Full Repair	Pull in berm, bring to grade, and provide drainage. 08/02 - REAF KC
419	Dozer Push	Needs Assessment	Full Repair	Pull in berm, bring to grade, and provide drainage. 08/02 - REAF KC
424	Dozer Push	Needs Assessment	Repair Full	Bring to grade and provide drainage. 08/05-REAF KC
425	Dozer Push	Needs Assessment	Repair Full	Bring to grade and provide drainage. 08/05 REAF KC
426	Dozer Push	Needs Assessment	Full Repair	Bring to grade and provide drainage. 08/05-REAF KC
427	Dozer Push	Needs Assessment	Full Repair	Bring to grade and provide drainage. 08/05 REAF KC
428	Dozer Push	Needs Assessment	Full Repair	Bring to grade and provide drainage. 08/05 REAF KC
429	Dozer Push	Needs Assessment	Full Repair	Bring to grade and provide drainage. 08/05 REAF KC
440	Dozer Push	Needs Assessment	Repair Full	Possible to use material and road fill. Bring to grade and provide drainage. 08/06 REAF KC
459	Dozer Push	Repair Needed	Full repair	pull in berms, scatter slash, seed 100x50ft. invasives present in area BM 8/23 LL Cleared 8/23
460	Dozer Push	Needs Assessment	masticate and chew, regrade and chip or reseed. READ Donnermeyer 08/27/2023 arch cleared.	
462	Dozer Push	Repair Needed	Repair Full	Dozer push and turnaround. Bring berm to grade, provide drainage, seed, cover with slash, barricade to prevent reuse. 08/07 REAF KC
464	Resource Location	Needs Assessment		
466	Dozer Push	Needs Assessment	Full repair	READ Donnermeyer 08/27/2023
470	Resource Location	Needs Assessment		
482	Landmark	Needs Assessment		
522	Bridge	Repair Needed	Removal of wrap when complete. REAF Lang 8/29/23 hand line around bridge, full repair, cover with slash, 3 person crew sufficient	
523	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
524	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
525	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
526	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
527	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
528	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
529	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
530	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
531	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
532	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
533	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
534	Dozer Push	Needs Assessment	full repair	READ Donnermeyer 08/27/2023
564	Stream Crossing	Needs Assessment	Full repair	Re-establish proper drainage. Soils/hydro READ should be present during repair
590	Bridge	Needs Assessment		
592	Dozer Push	Repair Needed	Full repair	pull in berms, scatter slash, seed BM 8/23
551	Culvert	Completed - Ready for Inspection	Hand crew - Clear out debris and remove gravel from uphill of culvert inlet. 08/13/23 REAF KC	
	Culvert	Needs Assessment	Clear debris, replace debris shield. 8/27 REAF Lang	