

# Repair Points - High Priority

FeatureStatus = 'Approved'  
 DeleteThis NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')  
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')  
 RepairPriority = High

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
152	Other	Needs Assessment		
43	Drop Point	Repair Needed		
160	Dozer Push	Completed - Inspected	Full repair	Pull in berms, seed and straw. cleared for arch by Slaton 8.2.23
71	Drop Point	Repair Needed	Light repair	Leave as a permanent parking area, seed with 5 bags of dry mix and mulch to prevent invasives.
4	Helispot	Completed - Inspected		
60	Drop Point	Repair Needed		remove flagging, no other repairs needed. BM 8/22
177	Repair Point	Repair Needed	Light Repair Meadow Repair	Seed late in season. No straw. 50% FERO and 50% DACA.
189	Other	Needs Assessment		
190	Repair Point	Repair Needed	Full repair	Seed, straw, block entrances, cover in veg (REAF Johannsen)100x200 ft BM8/22
29	Drop Point	Repair Needed		
27	Drop Point	Repair Needed		no repair needed BM 8/22
202	Repair Point	Repair Needed	Pull in berms, scatter veg, seed and straw 75x50ft BM 8/22	Pull in berms, scatter slash, seed and straw
205	Resource Location	Repair Needed	Repair Light	Pull in equipment ruts and bring to grade for erosion control.
208	Repair Point	Repair Needed	Yes	End of complete repair section. Check with Tbird - working on plan with Ptarmagin trails (forest partner)
209	Repair Point	Repair Needed	Yes	Replace boulders to block this area from OHV.
211	Repair Point	Repair Needed	Yes	Hide the line from the road and block entrance with tank trap type thing to prevent OHV use
10	Helispot	Repair Needed	Light repair	Mulch & seed with dry seed on sloped SE corner. 0910 READ Miller. REAF Maginel, 8/31. Seed area that has received forwarder and skidder and truck use. Area to be seeded is about 200 x 200 square feet.
34	Drop Point	Repair Needed		
610	Repair Point	In Progress	Yes	Mulch & seed. Block with large rocks to prevent ohv REAF BIRD 7/26. :: Mini-excavator repaired meadow dozer line and pulled back rocks to block parking area 9/12. REAF Van Norman. Still needs mulch and seed.
282	Repair Point	Repair Needed	Full repair	Mulch & seed 200 ft from road, pull in slash. 0911 READ Miller
130	Drop Point	Repair Needed		
333	Repair Point	Completed - Inspected	Repair Light. Block, waterbar and slash. REAF JRH 7/28	Old road prism/dozer line opened. REAF JRH 7/28
339	Landing or Log Deck	Repair Needed	Full repair	French broom growing across on 1503, pulled, but seed source could be present in landing. seed and mulch once logs are moved. REAF Martin 8/26
344	Resource Location	Repair Needed		handwork only, MIST Tactics, pull flagging
345	Landing or Log Deck	Repair Needed	Full repair	Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26
413	Repair Point	Completed - Inspected	remove when no longer needed	photos in ESA box folder
467	Repair Point	Repair Needed	Light repair	Mulch and seed with shaded dry seed mix. Cover with slash. 0911 READ Miller
519	Bridge	Completed - Inspected	remove when no longer needed	
109	Drop Point	Repair Needed	Light repair	Mulch & seed with dry seed mix along Rd 37 200ft on disturbed side. 0910 READ Miller
570	Repair Point	Repair Needed	Yes	Pull back berm through dozer line to access trail tread- pups trail
571	Repair Point	Repair Needed	Full	Dozer uprooted posts along road/trail
593	Repair Point	Completed - Inspected		
594	Dozer Push	Completed - Inspected		pull in berms, scatter slash, seed. ingasives present BM 8/23
613	Stream Crossing	Repair Needed	full repair stream crossing	coconut matting to maintain stability of steep drainage crossing. REAF Calvin 8/25 Div T approved to change status
617	Stream Crossing	Repair Needed	full repair, stream crossing	stabilize dozer line leading to stream with coconut matting. READ present during repair. REAF EL 8/25 DIV T approved to change status
615	Stream Crossing	Repair Needed	full repair, stream crossing	stabilize dozer line leading to stream with coconut matting. read present during repair. REAF EL 8/25 DIV T approved to change status.
	Repair Point	Repair Needed		
	Dozer Push	Repair Needed	Light repair	Push back and spread out soil, 20230909 READ miller
	Repair Point	Repair Needed	Light repair	Mulch & seed with dry seed mix 200ft from road, pull in slash. Small portion of seed spread over former log deck at top. 0910 READ Miller

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
	Repair Point	Repair Needed	Light repair	Add more mulch & seed newly disturbed area. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Seed 200ft from road. Already mulch and blocked. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch & seed newly disturbed area. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch & seed on sloped SE corner. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Seed 200 ft from road, already mulched. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch and seed with dry seed mix about 100' up dozer line and in small torn up area in front of dozer berm.9/10 REAF Van Norman
	Repair Point	Repair Needed	Light repair	Seed 200 ft from road, already mulched. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch and seed 200 ft both side of road intersect. Pull in slash. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Repair segment from road to road. Pull in berms, light slash and water bars; block access at road intersections to prevent OHV use. Mulch and seed within 200 feet of road. Use closed dry seed mix. 0911 READ Miller
	Repair Point	Needs Assessment	Light repair	Assess need for seed & mulch. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Pull in berms, light slash and water bars; block access at road intersections to prevent OHV use. Mulch and seed within 200 feet of road. Use dry open seed mix. 0911 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch and seed 200 ft both sides of road intersect. Pull in slash. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch & seed 200 ft from road. 0911 READ Miller
	Repair Point	Repair Needed	Full repair	Mulch & seed all 400 ft of line. 0911 READ Miller
	Repair Point	Repair Needed	Light repair	Mulch & seed 200 ft from road. 0910 READ Miller
	Repair Point	Repair Needed	Light repair	Add water bars and block off from road. Mulch and seed with shaded dry seed mix 200 ft from road. 0911
	Repair Point	Repair Needed	Light repair	Mulch and seed from DP 109 road intersection down the 37 rd.
	Repair Point	Repair Needed	Light repair	Pull in berms, light slash and water bars; block access at road intersections to prevent OHV use. Mulch and seed within 200 feet of road.
	Repair Point	Repair Needed	Light repair	Seed & Mulch steep section
	Repair Point	Repair Needed	Light repair	Seed all, Mulch 200ft from DP45
	Repair Point	Repair Needed	Full repair	Improve quality of burm pull back, waterbars and slash distribution REAF Di Mario 9/12/23.
	Repair Point	Repair Needed	Light repair	Seed & mulch
	Repair Point	Repair Needed	Light repair	Seed & Mulch, Coco mat by stream
	Repair Point	Repair Needed	Light repair	Seed all, Mulch 200 ft from road
	Repair Point	Repair Needed	Light repair	Seed dozer section
	Repair Point	Repair Needed	Light repair	Seed, invasive concern
	Repair Point	Repair Needed	Light repair	Seed & Mulch 200ft
	Repair Point	Repair Needed	Light repair	Seed all, Mulch first 200ft from road
	Repair Point	Repair Needed	Light repair	Seed & mulch all
	Repair Point	Repair Needed	Light repair	Seed & mulch up to treeline
	Repair Point	Repair Needed	Light repair	Seed & mulch all
	Repair Point	Repair Needed	Light Repair	Seed along Rd 202 & Mulch first 200 ft, Coco mat near culvert
	Repair Point	Repair Needed	Light repair	Seed & mulch 200ft on both side road
	Repair Point	Repair Needed	Light repair	Seed & mulch up to treeline
	Repair Point	Repair Needed	Full Repair	REAF REQUIRED ON SITE DURING REPAIR. Not feasible to transport straw to this location. Consider generating slash material from fuels treatment piles and cutting encroaching Douglas fir to cover line. Any trees cut, live or dead, shall not have a survey tag on bole REAF Di Mario 9/12/23.
	Repair Point	Repair Needed	Light repair	Seed & Mulch
	Repair Point	Repair Needed	Light repair	Seed & mulch
	Repair Point	Repair Needed	Full repair	Loosely consolidated bedrock, add water bars where feasible. Little to no slash, consider generating material by cutting small trees and brush REAF Di Mario 9/12/23.
	Repair Point	Repair Needed	Light repair	Seed & Mulch steep sections
	Repair Point	Repair Needed	Light repair	Seed & mulch all of dozer line, Coco mat where dozer line crosses road
	Repair Point	Repair Needed	Light repair	Seed & Mulch
	Repair Point	Repair Needed	Light repair	Leave as a permanent parking area, seed with 5 bags of dry mix and mulch to prevent invasives. 0911 READ Miller
	Repair Point	Repair Needed	Light repair	Seed & mulch