

INFRARED INTERPRETER'S DAILY LOG

Incident Name: Decker CO-RGF-001388	IR Interpreter(s): Elise Bowne elise.bowne@usda.gov	Local Dispatch Pueblo Dispatch 719-553-1600	Interpreted Size: NA Growth last period: NA
Flight Time: evening Flight Date: 10/02/2019	Interpreter(s) location: Denver, CO Interpreter(s) Phone: 303-517-7510	GACC IR Liaison: Elise Bowne GACC IR Liaison Phone: 303-517-7510	National Coordinator: Tom Mellin National Coord. Phone: 505-842-3845
Ordered By: Plans (970-903-1957)	A Number: A-50	Aircraft/Scanner System: N149Z / Phoenix	Pilots/Techs: N149Z Flight Crew Pilot: Johnson Pilot: Boyce Tech: Teats
IRIN Comments on imagery: No imagery – UTF Mechanical		Weather at time of flight:	Flight Objective: Map heat perimeter, intense heat, scattered heat, and isolated heat
Date and Time Imagery Received by Interpreter: NA		Type of media for final product: IR Daily Log	
Date and Time Products Delivered to Incident: NA		Digital files sent to: https://ftp.nifc.gov/public/incident_specific_data/rocky_mtn/2019/Decker/IR/20191003/ and email	
Comments / notes on tonight's mission and this interpretation: No flight tonight, due to mechanical issues with the aircraft Questions/Comments – Contact the interpreter through the contact info above.			