

SubLine Type	Collector Name	Length	Foot Comments	Repair Status	
100	Road as Completed Line	ortega	6195	1713 Road	Repair Needed
536	Completed Hand Line	Donley	7468	Proposed indirect	Repair Needed
102	Road as Completed Line	Donley	23209	Proposed indirect	Repair Needed
103	Completed Dozer Line	T Bruch Fobs	5071	This is a completed one blade wide dozer line. Line crosses private land at North end. Wet meadow repair necessary on private.	Repair Needed
104	Road as Completed Line	Hallam	10935	Road prepped by feller buncher and skidder	Repair Needed
537	Road as Completed Line	Megel DIV6, T Bruch FOBS, READ Carroll	3278	Road has been prepped and line is complete	Repair Needed
107	Completed Dozer Line	Megel DIV6, T Bruch FOBS; amnd LAKER, READ Carroll12564		Part of West Sand Creek line, completed dozer line, line was felled with feller buncher prior to line installation, logs are stacked in small turns along the entire length of the dozer line	Repair Needed
108	Completed Dozer Line	T. Stevens	2391	Needs saw prep	Repair Needed
109	Completed Dozer Line	T. Stevens	2340		Repair Needed
112	Access or Improved Road	Joe Murray	778		Repair Needed
114	Completed Dozer Line	Lipp	21078		Repair Needed
115	Completed Dozer Line	Hallam	5551	Line follows clear cut up top then dives into the north fork drainage. hand line continues on into drainage bottom	Repair Needed
116	Completed Dozer Line	Lipp	3123		Repair Needed
117	Road as Completed Line	Hallam	3993	Linking road to clear cuts	Repair Needed
118	Completed Dozer Line	Lipp	1032	Completed dozer line	Repair Needed
119	Completed Hand Line	Greg Gilbert - TFLD	866		Repair Needed
120	Completed Hand Line	Greg Gilbert - TFLD	138		Repair Needed
121	Completed Dozer Line	Greg Gilbert - TFLD	530		Repair Needed
124	Completed Dozer Line	Lipp	553		Repair Needed
125	Completed Hand Line	Lipp	424		Repair Needed
127	Completed Hand Line	Lipp	840		Repair Needed
128	Completed Hand Line	Joe Murray	2923	Eyebrow around CSU campus to the west, lined plumbed with laterals, sprinklers around upper student cabins and demo cabins	Repair Needed
129	Road as Completed Line	Lipp	2991		Repair Needed
130	Completed Hand Line	Lipp	296		Repair Needed
131	Road as Completed Line	Lipp	12338		Repair Needed
132	Road as Completed Line	T. Stevens	11331		Repair Needed
134	Completed Dozer Line	Lipp	3821		Repair Needed
135	Access or Improved Road	Phil Graham	11320	NFSR 259	Repair Needed
136	Completed Hand Line	Phil Graham	1867		Repair Needed
140	Access or Improved Road	Daniel Perkins, CRWB Maine #1	14321	Access to remote structures	Repair Needed
142	Road as Completed Line	Lipp	5728	Road around campground used as control line	Repair Needed
143	Access or Improved Road	Lipp	2475		Repair Needed
144	Completed Dozer Line	T. Stevens	708	Dozer line just west of Elkhorn Creek TH	Repair Needed
145	Completed Dozer Line	T. Stevens	1072	Dozer line on non-system trail?	Repair Needed
146	Completed Dozer Line	T. Stevens	7521	Prepped on west side. 50 foot prep	Repair Needed
147	Road as Completed Line	T. Stevens	2964	Secondary line	Repair Needed
149	Completed Hand Line	T Bruch FOBS	2162	handline on 70% slopes. line has been brushed 50 feet wide and jack piles on the green side, water bars will be needed extensively on much of the line and brush pulled back on the line too	Repair Needed
150	Completed Dozer Line	Lipp	1984		Repair Needed
151	Completed Hand Line	Lipp	578		Repair Needed
152	Completed Dozer Line	T Bruch FOBS	5382	dozer line complete	Repair Needed
153	Road as Completed Line	T. Stevens	3406	Mixture of road and drivable trail. Tight. T6 only. 50 foot prep on west side	Repair Needed
154	Completed Dozer Line	T. Stevens	1919	Prep on west side 50 foot	Repair Needed
155	Road as Completed Line	T. Stevens	1046	Old road bed opened by dozer	Repair Needed
156	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	518	Burned both sides	Repair Needed
157	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	558		Repair Needed
158	Completed Hand Line	Daniel Perkins, CRWB Maine #1	244		Repair Needed
159	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	906		Repair Needed
160	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	454		Repair Needed
161	Road as Completed Line	Daniel Perkins, CRWB Maine #1	372		Repair Needed
162	Completed Dozer Line	Daniel Perkins	927		Repair Needed
164	Road as Completed Line	Donley	10472	Mechanical work along road completed.	Repair Needed
165	Road as Completed Line	Donley	2066		Repair Needed
166	Completed Dozer Line	Lipp	1260		Repair Needed
167	Completed Dozer Line	Jake Wolff DIV F Trainee, READ Carroll	6736	One blade wide dozer line berms will need to be pulled back in and line will need to be closed and rehabbed	Repair Needed
168	Road as Completed Line	Jake Wolff DIV F Trainee, READ Carroll	6655	A feller buncher was used to clear this road approximately a chain wide.	Repair Needed
169	Road as Completed Line	repairs READ Carroll	3067		Repair Needed
172	Completed Hand Line	Lipp	5630	Change from planned to completed per branch.	Repair Needed
173	Completed Dozer Line	TBruch FOBS, READ Carroll	1245	Completed Dozer line ties into a large meadow at the terminus. Line is one chain wide was previously cut with a feller buncher And the logs were skidded to the landing located in the Clear cut	Repair Needed
175	Completed Dozer Line	Lipp	623		Repair Needed
176	Completed Dozer Line	Hallam	3098	Linking road to clear cuts	Repair Needed
177	Road as Completed Line	Donley updated by FORB Franks	1771	Completed. Update: not a dozer line, existing road, no evidence of dozer	Repair Needed
178	Road as Completed Line	Hallam, READ Carroll	3012	Linking road to clear cuts	Repair Needed
179	Completed Dozer Line	Hallam	512	Linking road to clear cuts	Repair Needed
180	Road as Completed Line	Lipp	26142	Change from planned secondary to road as completed line per branch.	Repair Needed
181	Access or Improved Road	NASFOR	1519	Improved F5 road 168 from Ben Delorain scout Ranch. About 1/4 mile private approved by ranch manager. Install water bars where needed.	Repair Needed
183	Completed Dozer Line	DIV5 R. Tumbow	10596		Repair Needed
184	Completed Dozer Line	T Bruch Fobs, READ Carroll	3076	this feature is a completed Dozer line that was placed on top of an admin Road	Repair Needed
187	Road as Completed Line	Lipp	2306	20' cut on both sides of road	Repair Needed
188	Completed Hand Line	TFLD Hatch	111		Repair Needed
189	Completed Dozer Line	Lipp	614		Repair Needed
190	Road as Completed Line	Lipp	25215	319 road prepped from Foxrot spike to H-93 but straight line NE was a mistake	Repair Needed
192	Completed Hand Line	Lipp	480	Handline to river. Follows old 2 track.	Repair Needed
195	Road as Completed Line	David Wolf	1671	On two track road	In Progress
196	Road as Completed Line	TFLD Sams	4796	Planned Handline off existing two track.	In Progress
198	Road as Completed Line	DIV VV	901	Gravel road and driveway using a ridge line feature. Some brushing along road may be needed	Repair Needed
199	Road as Completed Line	DIV VV	6338	Brushing on both sides is necessary. West of the road is light grassy fuels in Bobcat fire scar	Repair Needed
200	Road as Completed Line	DIV VV	914	Brushing will need to be done on both sides.	Repair Needed
201	Completed Dozer Line	Lipp	3400		Repair Needed
202	Completed Dozer Line	Lipp	3289		Repair Needed
203	Completed Dozer Line	Lipp	5185		Repair Needed
204	Access or Improved Road	dated FOBS Franks, Repair update by READ Carroll16968		Line is accessible by 4x4 high clearance from North end. Dozer line is blocked near the south end of line. Plumbed with 1.5 and 1". Every 100-200' is a rolled 1" hose with a nozzle.	Repair Needed
205	Road as Completed Line	Bostwick	1097	Point protection for fish hatchery	Repair Needed
210	Road as Completed Line	Lipp	32711		Repair Needed
211	Completed Dozer Line	Nbasford	8272		Repair Needed
212	Completed Dozer Line	C-68 / Donley	2973	UTV use only	Repair Needed
213	Completed Dozer Line	Columbine WFM	579		Repair Needed
214	Completed Dozer Line	Columbine WFM	7336	Converted from proposed dozer line. Ties into campground loops slightly further west than shown on map	Completed - Ready for Inspection
215	Access or Improved Road	Mario Orzco	4348	4x4 vehicle access road to Crosier Mt. Trail, or also called old sawmill road. This is also access to the single structure on top of this ridge.	Repair Needed
216	Completed Dozer Line	J. Searies	3069	Needs prepped with feller buncher	Repair Needed
217	Completed Dozer Line	David Vester	6974		Repair Needed
218	Access or Improved Road	Shesha Koch	3113	UTV / ATV / skiddering access line to 177 road	Repair Needed
219	Completed Dozer Line	Skoch_nfc	2921	Dozer line to access fire	Repair Needed
220	Completed Dozer Line	Skoch_nfc	1206	Control line	Repair Needed
221	Completed Dozer Line	Skoch_nfc	1060	Dozer line as control line	Repair Needed
222	Completed Dozer Line	Skoch_nfc	1084		Repair Needed
223	Completed Dozer Line	Skoch_nfc	2039		Repair Needed
224	Completed Dozer Line	Skoch_nfc	4085		Repair Needed
225	Completed Dozer Line	Skoch_nfc	1295		Repair Needed
226	Completed Hand Line	Columbine WFM/ update FOBS Franks	572	Short sections of hand line connected by beaver pond. Update: handline has filled in with water from beaver pond	Other - See Comments
227	Road as Completed Line	Columbine WFM	958	Existing 2 track	Repair Needed
228	Completed Dozer Line	Columbine WFM	1324		Repair Needed
229	Completed Dozer Line	Columbine WFM/ update FOBS Franks	5327	Plumbed with hose lay	Repair Needed
231	Road as Completed Line	Skoch_nfc	12098	Cut by equipment	Repair Needed
232	Completed Dozer Line	Skoch_nfc	1166	Dozer line with equipment cut	Repair Needed
233	Completed Dozer Line	Skoch_nfc	8934	Dozer line with equipment cut	Repair Needed
234	Access or Improved Road	Skoch_nfc	10067	Access for ATV/UV minimal scrape	Repair Needed
235	Completed Hand Line	Yeoman	1111		Repair Needed
236	Completed Dozer Line	Yeoman	1779	Dozer line along old road/previous dozer line	Repair Needed
237	Completed Hand Line	Yeoman	698	Hand line with hose lay	Repair Needed
238	Completed Dozer Line	Yeoman	1596	Light dozer push. Unsure if this was completed by fire operations or private landowners.	Repair Needed
239	Completed Dozer Line	Yeoman	1700		Repair Needed
240	Completed Hand Line	Yeoman	413		Repair Needed
241	Completed Dozer Line	Yeoman	1963		Repair Needed
242	Completed Hand Line	Yeoman	1758		Repair Needed
243	Completed Dozer Line	Yeoman	1027		Repair Needed
244	Completed Dozer Line	Yeoman	8526		Repair Needed
245	Completed Dozer Line	Yeoman	258	Changed from hand to dozer. FOBS Franks 10/13/2020	Repair Needed
246	Completed Dozer Line	Yeoman	164		Repair Needed
247	Completed Dozer Line	Yeoman	267	Changed hand line to dozer line. FOBS Franks 10/13/2020	Repair Needed
248	Road as Completed Line	Lipp	2357	Proposed dozer line down a two track	Repair Needed
249	Completed Dozer Line	Lipp	5032		Completed - Ready for Inspection
250	Completed Dozer Line	Jamie Geerdes	11099	Dozer line off the 225	Repair Needed
251	Completed Dozer Line	Lipp	9994		Repair Needed
252	Completed Dozer Line	Lipp	7074		Repair Needed
253	Completed Dozer Line	tobates_nfc, REAF	6127	route was originally just unbladed access, till a dozer operator took it upon himself to "improve" the access by blading it. cut trees are off to side.	Repair Needed
254	Completed Dozer Line	tobates_nfc, REAF	4843	517B used to access the fire edge via extension. dozer has subsequently bladed road.	Repair Needed
255	Access or Improved Road	tobates_nfc, REAF	4469		Repair Needed
256	Access or Improved Road	tobates_nfc, REAF	13755		Repair Needed
257	Road as Completed Line	Lipp	5231	Prepped south of road. **needs to be chipped	Repair Needed
258	Road as Completed Line	Jamie Geerdes TFLD	6645	171L UTV only	Repair Needed
259	Completed Hand Line	Jamie Geerdes TFLD	786		Repair Needed
260	Completed Dozer Line	Jamie Geerdes TFLD	1871		Repair Needed
261	Completed Dozer Line	Jamie Geerdes TFLD	1073		Repair Needed
262	Completed Dozer Line	Daniel Perkins, FORB	290	30' mechanical thinning both sides	Repair Needed
263	Completed Dozer Line	Daniel Perkins, FORB	1354	1 chain of mechanical thinning on black side	Repair Needed
264	Completed Dozer Line	Daniel Perkins, FORB	656	access line, not fireline	Repair Needed
265	Completed Dozer Line	Daniel Perkins, FORB	751	access line, not fireline	Repair Needed
266	Access or Improved Road	Daniel Perkins, FORB	1356	No prep work to road segment	Repair Needed
269	Road as Completed Line	Daniel Perkins, FORB	8771		Repair Needed
270	Road as Completed Line	Daniel Perkins, FORB	1334		Repair Needed
271	Road as Completed Line	Daniel Perkins, FORB	15472	Road recently improved by grader. Not sure if work was fire related.	Repair Needed
272	Completed Dozer Line	Lipp	2426		Repair Needed
273	Completed Dozer Line	Lipp	6437		Repair Needed
274	Completed Dozer Line	T Bruch FOBS, READ Carroll	1642	Completed Dozer line	Repair Needed
275	Road as Completed Line	T Bruch FOBS, READ Carroll	866	Ties into meadows on both ends	Repair Needed
276	Completed Dozer Line	tobates_nfc, REAF	1232	Road is used here as a line that ties into the dozer line area was masticated	Repair Needed
277	Completed Dozer Line	tobates_nfc, REAF	226	initial direct line.	Repair Needed
278	Completed Dozer Line	tobates_nfc, REAF	2441	dozer line down to flowing trib or Roaring creek. dozer tracked through creek. see photo point.	Repair Needed
279	Completed Dozer Line	tobates_nfc, REAF	2047	direct line. walked actual completed line. stopped at a seep incursion.	Repair Needed
280	Completed Dozer Line	tobates_nfc, REAF	3068	stopped to collect point	Repair Needed
281	Completed Dozer Line	tobates_nfc, REAF	374	ended at stream crossing	Repair Needed
282	Completed Dozer Line	tobates_nfc, REAF	470	spur	Repair Needed
283	Completed Dozer Line	tobates_nfc, REAF	6919	top part is indirect, lower down is direct. actual line walked.	Repair Needed
284	Completed Dozer Line	tobates_nfc, REAF	3409		Repair Needed
285	Completed Dozer Line	Tobates_nfc, REAF	1978	Line down from helispot circling spot then connecting to completed dozer line.	Repair Needed
287	Completed Dozer Line	Daniel Perkins, FORB, READ Carroll	3153	Dozer line on top of handline.	Repair Needed
288	Completed Dozer Line	TFLD Jamie Geerdes	1457		Repair Needed
289	Completed Dozer Line	TFLD Geerdes	213		Repair Needed
291	Completed Dozer Line	TFLD Geerdes	2855		Repair Needed
292	Road as Completed Line	Daniel Perkins, FORB	78640	30-60' brushed and limbed on black side	Repair Needed
293	Completed Dozer Line	Lipp	1482		Repair Needed
294	Completed Dozer Line	Lipp	801		Completed - Inspected
295	Completed Dozer Line	Lipp	538		Completed - Inspected
296	Completed Dozer Line	Lipp	941		Completed - Inspected
297	Completed Dozer Line	Lipp	1352		Completed - Inspected
298	Completed Dozer Line	Lipp	261		Completed - Inspected
299	Completed Dozer Line	TFLD Geerdes	1942		Repair Needed
300	Completed Hand Line	TFLD Geerdes	234		Repair Needed
301	Completed Hand Line	TFLD Geerdes	175		Repair Needed
302	Completed Hand Line	TFLD Geerdes	209		Repair Needed
304	Completed Dozer Line	Daniel Perkins, FORB	360		Repair Needed
305	Completed Dozer Line	Daniel Perkins, FORB	1256		Repair Needed
306	Completed Dozer Line	Daniel Perkins, FORB	2583		Repair Needed
307	Completed Dozer Line	T bruch Fobs, READ Carroll	624	Process and remove timber material. Leave slash for rehab. Dozer line in cut timber sale unit	Repair Needed
308	Completed Dozer Line	READ Laura Aker	335		Completed - Inspected
312	Completed Dozer Line	T Bruch Fobs	143		Repair Needed
313	Completed Hand Line	T bruch Fobs	216		Repair Needed
314	Completed Dozer Line	T bruch Fobs	254		Repair Needed
315	Completed Hand Line	T Bruch Fobs	898		Repair Needed
316	Completed Hand Line	T bruch Fobs	385		Repair Needed
317	Road as Completed Line	T Bruch Fobs	7839	517D road Has been treated on both sides with a feller Buncher and possibly a masticator most piles have been chipped line is approximately 125 feet wide. Prep on the road stops here.	In Progress
318	Access or Improved Road	Lipp	6992	Improved Road Submitted from READ Avenza	Completed - Ready for Inspection
319	Completed Dozer Line	Lipp	1609	Submitted from READ Avenza	Completed - Ready for Inspection
320	Completed Dozer Line	Lipp	921	Wided Road Submitted from READ Avenza	Repair Needed
321	Completed Dozer Line	Lipp	388	Submitted from READ Avenza	Completed - Inspected
322	Completed Dozer Line	Daniel Perkins, FORB/update FOBS Franks	146	likely done by landowner due to appearance: update, land owner stated it was them who put dozer line in	Repair Needed
323	Completed Dozer Line	Daniel Perkins, FORB/ update FOBS Franks	412	likely done by landowner due to appearance: update, land owner stated it was not them who put dozer line in	Repair Needed
324	Completed Dozer Line	Daniel Perkins, FORB/ update FOBS Franks	328	likely done by landowner due to appearance: Update,land owner stated it was not them that put in dozer line	Repair Needed
325	Completed Dozer Line	Daniel Perkins, FORB	388		Repair Needed
326	Completed Dozer Line	Daniel Perkins, FORB	819		Repair Needed
327	Completed Dozer Line	Daniel Perkins, FORB	1553		Repair Needed
328	Completed Dozer Line	Daniel Perkins, FORB	5241		Repair Needed
329	Completed Dozer Line	Daniel Perkins, FORB	993		Repair Needed
330	Completed Dozer Line	Daniel Perkins, FORB	1463		Repair Needed
331	Completed Dozer Line	Daniel Perkins, FORB	780		Repair Needed
332	Completed Dozer Line	Daniel Perkins, FORB	2004		Repair Needed
333	Completed Dozer Line	Daniel Perkins, FORB	968	possibility done by landowner due to appearance	Repair Needed
334	Completed Dozer Line	Daniel Perkins, FORB	466	possibility done by landowner due to appearance	Repair Needed
335	Completed Dozer Line	Daniel Perkins, FORB	504		Repair Needed
336	Completed Hand Line	Daniel Perkins, FORB	589		Repair Needed
337	Completed Dozer Line	Daniel Perkins, FORB	224		Repair Needed
338	Completed Dozer Line	Daniel Perkins, FORB	756		Repair Needed
339	Completed Dozer Line	Lipp	2165		Repair Needed
340	Completed Dozer Line	Daniel Perkins, FORB	1534		Repair Needed
341	Completed Dozer Line	T Bruch Fobs	263		Repair Needed
342	Completed Dozer Line	T Bruch Fobs	416		Repair Needed
343	Completed Dozer Line	T Bruch Fobs	1156		Repair Needed
344	Completed Dozer Line	T Bruch Fobs	2451	2 blades wide	Repair Needed
345	Completed Dozer Line	T Bruch Fobs	1941	double blade dozer lone	Repair Needed
346	Completed Dozer Line	T Bruch Fobs	6086		Repair Needed
347	Completed Dozer Line	T Bruch Fobs	1568		Repair Needed