

		and push up slope from drainage bottom.	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/16/22,ARC seeded,J.Ayers,ARCH, 6/29 REAF DRI hand crew repaired this dozer line on old road	water bars, knock down berms, more slash if possible	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	from Josh Goldstein		Unknown	Not Cleared
Completed Dozer Line		Repaired dozer burns in creek bottom (Jremers_nifc 6/20)	Unknown	Not Cleared
Completed Dozer Line	Hand drawn based on READ Chamberlain	FSR 152 C	High	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		No repair needed per landowner request	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/20/22		Unknown	Not Cleared
Completed Dozer Line	J.Ayers, 06/20/22	Completed 6/21/22 READ Merrifield	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers, 06/20/22	Completed 6/21/22 READ Merrifield	Unknown	Cleared for Hand Crew Repair
Completed Dozer Line	J.Ayers, 06/20/22	Completed 6/21/22 READ Merrifield	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers, 06/20/22	Completed 6/21/22 READ Merrifield	Unknown	Cleared for Hand Crew Repair
Completed Dozer Line		reseed with grass, pull in burn, hay bales recommended for erosion control.	High	Not Cleared
Completed Dozer Line	Two blades wide.	Water bar, pull slash.	Unknown	Not Cleared
Completed Dozer Line		6/24: REAFBullock inspected and complete. 6/23: REAF Bullock needs slash pulled and seeded. Water bar per rehab specs. On a 37-40% slope, pull existing slash over line, especially at road intersections	Unknown	Not Cleared
Completed Dozer Line	J.Ayers06/22/22,ARCH Cuts off a switchback.	Waterbar, cover w slash, knock down dozer berms, block access from campsite. Reestablish drainage near bottom	High	Cleared for Operations

Completed Mixed Construction Line		Creek Wash used as line	6/24: REAFBullock inspected and complete.	Unknown	Not Cleared
Completed Mixed Construction Line		Road improvements with DOZ.		Low	Not Cleared
Completed Mixed Construction Line		Check feature more scouting needed 6/14: single blade dozer line along old 2-track. Brushing/bucking on both sides with prep for chipping on one side	6/24: REAFBullock inspected and complete	Unknown	Not Cleared
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Repaired to landowner specs added Waterbars where needed (Jremers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		No repair recommended - road in good shape. (amckeith_nifc 6/19)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Minimal repair needed. Smoothed section of existing road. (amckeith_nifc 6/19)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Tracked through. No repair to existing road required. (amckeith_nifc 6/19/22)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		No repair recommended. Existing road in good shape. (amckeith_nifc 6/19)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Existing ranch road, improved with water bars. (amckeith_nifc 6/17)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC			Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Water bar construction on steep section of dozer push (amckeith_nifc 6/19)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Repaired to	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Repaired to landowner specs added Waterbars where needed (Jremers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line				Unknown	Not Cleared

Completed Road as Line	522 Road. Improved road travel conditions with some water turnouts. Road bladed. No veg prep work but is in scattered junipers and grass.	6/24: REAFBullock inspected and complete. Much of the road has flat blade work with berms on each side of the road which will channel water. Add or reinstall water turn outs and rolling grade dips, particularly on the steeper sections.	Unknown	Not Cleared
Completed Road as Line	522 Road. Improved road travel conditions with some water turnouts. Road bladed. No veg prep work but is in scattered junipers and grass.	6/25: REAFBullock inspected and complete. Much of the road has flat blade work with berms on each side of the road which will channel water. Add or reinstall water turn outs and rolling grade dips, particularly on the steeper sections.	Unknown	Not Cleared
Completed Road as Line	Road with some minimal cutting as prep. Road is in good condition and the few cut materials have been scattered.		Unknown	Not Cleared
Completed Road as Line	Originally labeled as a dozer line but it is Road 4112 improved.		Unknown	Cleared for Mechanical Repair
Other	ATV UTV trail		Unknown	Not Cleared
Other			Unknown	Not Cleared
Other	Fuel type change. May be a good location if needed for possible burn operations.	6/24: REAF Bullock no impacts noted	Unknown	Not Cleared
Other	Fuel type change. May be a good location if needed for possible burn operations.	6/24: REAFBullock no impacts noted	Unknown	Not Cleared
Other	Fuel type change. May be a good location if needed for possible burn operations.	6/24: REAFBullock no impacts noted	Unknown	Not Cleared
Other	Fuel type change. May be a good location if needed for possible burn operations.	6/24: REAFBullock no impacts noted	Unknown	Not Cleared
Other	If fire reaches this point consider bringing fire south from Apache peak trail / hand line South to the next viable check feature.		Unknown	Not Cleared
Other	Don't show on map yet. Two-track road, narrow, grown over with grass. Very rough. Do not recommend a truck. Could be opened up with a dozer or improved as a handline.		Unknown	Not Cleared
Other	Access trail. Old road. Accessible by foot. May be useful in a firing/burnout operation. Fresh Bear tracks. Also, a Goshawk.	6/24: REAFBullock inspected and complete.	Unknown	Not Cleared
Other	Access to "Black Range Ranch". Narrow road. Limited turnaround spots.		Unknown	Not Cleared
Other	All flagging on this line pulled.		Unknown	Not Cleared
Other	All flagging pulled on this line.		Unknown	Not Cleared
Repair Line	Road had been damaged from equipment; needs DZ work.	See road repair notes	Medium	Not Cleared
Repair Line			Unknown	Not Cleared
Road Repair	This portion of the 522 Road was rerouted. Water bars were installed and some branches scattered on the old road bed	6/21: Waterbars, berms and slash a scattered, inspected	Unknown	Not Cleared
Road Repair		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Not Cleared
Road Repair			Unknown	Not Cleared
Road Repair	Left open per landowners request. Smoothed road bed for better UTV access		Unknown	Not Cleared