

Community Dozer Repair West




0 0.15 0.3 0.6 0.9 1.2 Miles

Repair Standards

- Full Repair
- Partial Repair
- No Repair Needed
- Maintain ATV Trail
- Special Repair Concern

Full explanation of repair standards is in attachment.



Community Dozer Repair East




0 0.15 0.3 0.6 0.9 1.2 Miles

Repair Standards

- Full Repair
- Partial Repair
- No Repair Needed
- Maintain ATV Trail
- Special Repair Concern

Full explanation of repair standards is in attachment.



Community Dozer Repair Standards:

Full Repair: Spread berms and slash back over the entire bladed surface, restore natural contour, and block the line to OHV access. Line is closed.

Partial Repair: Break down berms and spread material to reduce exposed mineral soil. Tease out and retain firewood-sized material on site to the greatest extent possible.

No Repair Needed: Landowner has directed that the line be left as-is. No work required.

Maintain ATV Trail: Break down berms and distribute vegetation over the bladed surface, leaving a passable 6-ft ATV trail. Do not block.

Special Repair Concerns:


1. Survey Marker in the ground. Cap is missing. Attempt to locate and work around. Do Not Destroy, if possible.



3. Dozed slash blocking preexisting pull-thru access. Reestablish access.



2. Pull slash from unburned forest and consolidate into few large piles for winter burning. Owner hopes to create new driveway over dozer scrape. Spread berms.



4. Level berm, but retain open dozer line.

