



### Suppression Repair

**Suppression Repair Points**

⊕	Bridge	Ⓜ	Loose and Scatter Trees
⊗	Cattleguard Damage	Ⓜ	Meadow Damage
⊗	Chipping Slash	Ⓜ	Other
⊗	Culvert Damage	Ⓜ	Retardant Avoidance Area
⊗	Dozer Push	Ⓜ	Retardant Track Point
⊗	Drop Point	Ⓜ	Road Needs Repair
⊗	Equipment Found	Ⓜ	Safety Zone
⊗	Fence Damage	Ⓜ	Staging Area
⊗	Gate	Ⓜ	Water Course Crossing
⊗	Hand Line Repair	Ⓜ	Water Drafting Location
⊗	Hazard Tree	Ⓜ	Waterbar Needed
⊗	Helispot		

**GRAY = COMPLETED**

**Suppression Repair Status Masking**

—	GPS Verified - No Assessment
—	Not GPS Verified - No Assessment
—	Repair Needed
—	Completed - Needs READ Approval
—	Completed - Approved

### National Parks Trails

**DESIGNED USE**

- 4WD > 50 - FOUR-WHEEL DRIVE VEHICLE > 50"
- ATV - ALL TERRAIN VEHICLE
- MTRCYCL - MOTORCYCLE

**Suppression Repair**

**Mendocino Complex Ranch Fire Grindstone NP CA-MEU-008674**

8/27/2018

**Mendocino Complex Ranch Fire - Grindstone NP**

**CA-MEU-008674**

**Suppression Repair**

**August 27, 2018**

**Ownership**

- Other State Lands
- USDA Forest Service
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

NAD83 UTM Zone 10  
Contour Interval: 40 ft.  
Produced: 8/27/2018 2:52:29 PM

0 0.25 0.5 Miles 1:18,000