


- Suppression Repair Points**
- PointType, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Pile, Repair Needed
 - Drop Pile, Completed - Approved
 - Equipment Found, Repair Needed
 - Equipment Found, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Leak and Scatter Tank, Repair Needed
 - Leak and Scatter Tank, Repair Needed
 - Machine Damage, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Resistant Track Pile, Repair Needed
 - Resistant Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Completed - Approved
 - Water Course Location, Repair Needed
 - Water Course Location, Repair Needed
 - Watercourse Needed, Repair Needed
 - Watercourse Needed, Completed - Approved

SUPPRESSION REPAIR, 09/15/18
Div K

SoCal IMT 3 GIS
September 14, 2018
2154

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 15, 2018
0600
SUPPRESSION REPAIR
Div K

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Uncontrolled Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/15/18
Div K

SUPPRESSION REPAIR, 09/15/18
Div K