



ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN	ID	APN																																								
30	000-110-00-11	63	011-000-00-11	148	011-000-00-11	198	011-000-00-11	230	011-000-00-11	262	011-000-00-11	292	011-000-00-11	322	011-000-00-11	352	011-000-00-11	382	011-000-00-11	412	011-000-00-11	442	011-000-00-11	472	011-000-00-11	502	011-000-00-11	532	011-000-00-11	562	011-000-00-11	592	011-000-00-11	622	011-000-00-11	652	011-000-00-11	682	011-000-00-11	712	011-000-00-11	742	011-000-00-11	772	011-000-00-11	802	011-000-00-11	832	011-000-00-11	862	011-000-00-11	892	011-000-00-11	922	011-000-00-11	952	011-000-00-11	982	011-000-00-11	1000	011-000-00-11

Repair Status

- Completed - Inspected
- In Use - Fire Management
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Assessment Needed

Other Symbols

- Camp
- Culvert
- Dip Site
- Spot Fire
- Water Source
- Division Break
- Fence - Cut/Damaged
- Other - See Comments
- Hellspot
- Mobile Weather Unit
- Repeater
- Spot Fire
- Water Source
- Division Break
- Uncontrolled Fire Edge

Line Types

- Contained Line
- Completed Dozer Line
- H - H Completed Hand Line
- Completed Burnout
- BLM Field Office Boundary
- Forest Service Boundary
- USFS Wilderness Boundary
- Wilderness Study Areas Boundary
- Tulead DuckFlat CRA Boundary
- BLM Ownership
- Forest Service Ownership

REPAIR

W-5 COLD SPRINGS

CA-NOD-004727

09/06/2020

Sum of Completed Inspected: 81,654.00 ft.

Sum of Completed Ready for Inspection: 0.00 ft.

Sum of In Progress: 58,868.00 ft.

Sum of Repair Needed: 3,050.00 ft.

Sum of No Repair Needed: 8,643.00 ft.

Sum of Other: 0.00 ft.

Sum of Assessment Needed: 264,413.00 ft.

Scale: 1:45,000

Map Updated: 9/4/2020 23:52