


REPAIR PILOT

South Fork Complex September 19, 2023

REPAIR PILOT CA-SHF-001004 September 19, 2023



		Pump	Staging Area	Retardant in Avoidance Area	Internet Access	Stream/River	Repair Status	In Progress	Other - See Comments	In Progress
		Water Tank	Other	Repair Point	Hazard	Stream/River Intermittent	In Use - Fire Management	Completed - Ready for Inspection	Completed - Inspected	Completed - Ready for Inspection
		Sling Site	Bridge	Landing or Log Deck	Water Source	Local Roads	Needs Assessment	Completed - Inspected	Completed - Inspected	Completed - Inspected
		Drop Point	Road Repair	Doter Push	Lake / Pond	Dirt Roads	Repair Needed	No Repair Needed	No Repair Needed	No Repair Needed
						Trails				Other - See Comments

0 0.1 0.1 0.3 0.4 0.6 Miles

Datum: NAD 1983 UTM Zone 10N

