


REPAIR PILOT

South Fork Complex September 20, 2023

REPAIR PILOT CA-SHF-001004 September 20, 2023



Legend

		Pump	Staging Area	Retardant in Avoidance Area	Internet Access	Stream/River	In Use - Fire Management	Other - See Comments	In Progress	In Use - Fire Management	Other - See Comments
		Water Tank	Other	Repair Point	Hazard	Stream/River Intermittent	Completed - Ready for Inspection	Completed - Inspected	Completed - Ready for Inspection	Needs Assessment	No Repair Needed
		Sling Site	Bridge	Landing or Log Deck	Water Source	Local Roads	No Repair Needed	No Repair Needed	Completed - Inspected	Repair Needed	Repair Needed
		Drop Point	Road Repair	Doter Push	Lake / Pond	Dirt Roads			No Repair Needed		Repair Needed
						Trails					

Datum: NAD 1983 UTM Zone 10N