



Repair Legend

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping Needed

GISS_Misc2	FeatureCategory	RepairStatus	RepairsNeeded	Label	LengthFeet
165	Completed Road as Line	Repair Needed	Chip slash along road. REAF BGOMEZ, 5/10/24	Chip	17842
101	Completed Road as Line	In Progress	ARCH Leonard cleared 9/4 // Chipilla Self feeding chipper. Broadcast chips. Type 2 excavator to assist in operation. Estimated 3 days. REAF Olson 9/15	Chip	7097
106	Completed Road as Line	Repair Needed	Chip accessible masticated vegetation along both sides of roadway where available. REAF B Code, 5/10/24.	Chip	7253
107	Completed Road as Line	Repair Needed	Improved road: widened and mastication along this section of road. repairs: slash needs chipped, any soil piles need pulled in and smoothed out.	Chip	351
117	Access or Improved Road	Repair Needed	Road should be graded with either rolling dips or punch outs or both in steep areas. Equipment: Grader and water tender Engineer or Hydro needs Meeting 5/15/23.	Chip	18136

GISS_Misc2	FeatureCategory	Lat(WGS84_DDM)	Long(WGS84_DDM)	RepairStatus	RepairsNeeded
120	Dozer Push	41° 45.167' N	123° 53.490' W	Repair Needed	Need large chipper, masticator and excavator to pull out trees and brush that are on edge of road. Chips should be spread out on barren ground. Root wads need to be cut off and dispersed over the bank 6 hours work Reaf Cann 9-15-23.
134	Repair Point	41° 45.430' N	123° 54.531' W	Repair Needed	Remove and chip slash pile on road. REAF B Code, 5/10/24.
133	Dozer Push	41° 45.423' N	123° 54.513' W	Repair Needed	Pullback berms. Remove large vegetation pile in the middle of road. REAF B Code, 5/10/24.
132	Dozer Push	41° 44.391' N	123° 53.511' W	Repair Needed	Remove berm and slash off roadway. Spread slash in open area on inside of turn, if needed. REAF BGOMEZ, 05/10/24
128	Dozer Push	41° 44.343' N	123° 53.424' W	Repair Needed	corner has been widened, presence of larger berms of soil and slash. arch platt 9/15/23
131	Dozer Push	41° 44.501' N	123° 53.495' W	Repair Needed	Remove berm and pull slash on the curve of the road. Spread slash on shoulder if needed. REAF BGOMEZ, 05/10/24
127	Dozer Push	41° 44.722' N	123° 53.326' W	Repair Needed	widen corner to about 70'. larger piles of soil and slash. Platt 9/15/23
129	Dozer Push	41° 45.164' N	123° 53.472' W	Repair Needed	FULL REPAIR Pull in slash and naturalize. // Large chipper or tub grinder needed to chip large quantities of trees and brush. An excavator may be needed to move trees from down the bank up to the road. Reaf Cann 9-16-23.
	Dozer Push	41° 43.68915113' N	123° 54.57014351' W	Repair Needed	Pull back linear berm on side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.67253156' N	123° 54.52809702' W	Repair Needed	Pull back linear berm on outboard side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.47909789' N	123° 54.87643032' W	Repair Needed	Pull back linear berm on side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.42299883' N	123° 54.91626124' W	Repair Needed	Pull back linear berm on outboard side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.37870356' N	123° 54.96590784' W	Repair Needed	Pull back linear berm on outboard side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.39761506' N	123° 55.01786648' W	Repair Needed	Pull back linear berm on outboard side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 43.2322807' N	123° 54.88757452' W	Repair Needed	Pull back linear berm on outboard side of road to allow for water drainage. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 44.2001678' N	123° 53.3562268' W	Repair Needed	Remove berm and slash from edge of roadway. REAF BGOMEZ, 05/10/24
	Dozer Push	41° 44.36277930' N	123° 53.43671977' W	Repair Needed	Remove berm and slash from edge of roadway. REAF BGOMEZ, 05/10/24
132	Dozer Push	41° 44.391' N	123° 53.511' W	Repair Needed	Remove berm and slash off roadway. Spread slash in open area on inside of turn, if needed. REAF BGOMEZ, 05/10/24

- Drop Point
- ▲ Dozer Push
- Primitive Road
- 4WD
- ⊕ Water Source
- Paved Road
- - - Closed Roads
- - - Closed Road
- ▲ Repair Point
- Gravel Road
- Local Road

SPRING SUPPRESSION REPAIR

Smith River Complex - Fox Ridge Repair Area

94,639 acres as of 11/13/2023
Map Date 05/17/2024

INTERAGENCY INCIDENT MANAGEMENT TEAM

FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE

SIX RIVERS
National Forest

1:9,000 NA83 UTM 10N

Smith River Complex
CA-SRF-000968
REPAIR