

**Lime Complex, Slide Fire
Suppression Repair Map
CA-SHF-1041**
August 21, 2008



REPAIR FOR SLIDE FIRE

- █ COMPLETED REPAIR
- Previous restoration needing repair
- Equipment, treatment**
- Excavator,
- Excavator, Open Drainage
- Excavator, Pull Fill
- ▲ Excavator, Pull Woody Back
- Equipment, recommendation**
- Dozer, Waterbar
- - - Excavator, Pull in Berm
- Excavator, Waterbar
- N/A, Waterbar

