




**Whittier**  
**Suppression Repair**  
**CA-LBOR 001770**  
**July 25, 2017**  
**SW Quadrant**

- Highway
- Road - Light Duty - Dirt
- Road - Light Duty - Unspecified Composition
- Road - Unimproved
- Trail



	Division		Fence, Repair Needed		Natural Barrier
	Fixed Wing Retardant		Gate, Repair Needed		Dozer Line
	Rotor Retardant		Helispot, Repair Needed		Dozer on Road
	Other Large Dozer Push (parking area etc.), Repair Needed		Other, Repair Needed		Hand Line
	Helispot, Repair Approved		Sling Site, Repair Needed		Road Repair
	Water Development & Draft Site, Repair Approved		Trails, Repair Needed		Repair Needed
	Culverts, Repair Needed		Water Development & Draft Site, Repair Needed		Stage 1 Repair Complete
	Drop Point, Repair Needed		Wildlife Habitat Concern		Repair Approved
	Equipment Found				

**Branch II**