



Suppression Repair

Dolan Fire
CA-LPF-002428
10/19/2020 DAY

124,924 acres at 9/28/2020 2000 hrs



- Clamp
- Clean Up Area
- Drop Point
- Dozer Push
- Fence - Cut/Damaged
- Hazard Tree
- Incident Command Post
- Unexploded Ordnance
- Repair Point
- Safety Zone
- Staging Area
- Value at Risk
- Division Break
- Access or Improved Road, No Repair Needed
- Access or Improved Road, Repair Needed
- Completed Dozer Line, Completed - Inspected
- Completed Dozer Line, No Repair Needed
- Completed Dozer Line, Other - See Comments
- Completed Dozer Line, Repair Needed
- Completed Hand Line, Completed - Inspected
- Completed Hand Line, No Repair Needed
- Completed Hand Line, Repair Needed
- R - R Road as Completed Line, Completed - Inspected
- R - R Road as Completed Line, No Repair Needed
- R - R Road as Completed Line, Repair Needed
- Dolan Repair Area
- Restricted Area
- CA State Park
- Ventura Wilderness
- The Pacific Ocean
- Wildfire Daily Fire Perimeter



EAIMT GISS
10/19/2020 0238
Acres from IR and field reports
NAD 1983 California Teale Albers

