


Suppression Repair

Dolan Fire
 CA-LPF-002428
 10/27/2020 DAY

124,924 acres at 9/28/2020 2000 hrs



	Microsoft Building Footprints (MSBFP)		Division Break		R - R - R -
	Summits		Completed - Inspected		Dolan Repair Area
	Bridge		Repair Needed		Restricted Area
	Camp		No Repair Needed		Ventana Wilderness
	Clean Up Area		Other - See Comments		The Pacific Ocean
	Drop Point		Unknown		Wildfire Daily Fire Perimeter
	Dozer Push		Access or Improved Road, Completed - Inspected		Trail
	Fence - Cut/Damaged		Access or Improved Road, No Repair Needed		Expressway
	Helibase		Access or Improved Road, Repair Needed		Secondary Hwy
	Helispot		Completed Dozer Line, Completed - Inspected		Local Connector
	Incident Command Post		Completed Dozer Line, Completed - Ready for Inspection		Local Road
	Repair Point		Completed Dozer Line, No Repair Needed		Ramp
	Repeater		Completed Dozer Line, Other - See Comments		4WD
	Safety Zone		Completed Dozer Line, Repair Needed		Tunnel
	Sling Site		Completed Hand Line, Completed - Inspected		Township/Range
	Staging Area		Completed Hand Line, No Repair Needed		Land Grant
	Stream Crossing		Completed Hand Line, Repair Needed		Section
	Structure Wrap		Road as Completed Line, Completed - Inspected		Runway
	Water Development or Draft Site		Road as Completed Line, No Repair Needed		

