


# Suppression Repair

Dolan Fire  
 CA-LPF-002428  
 11/2/2020 DAY

124,924 acres at 9/28/2020 2000 hrs

	Microsoft Building Footprints (MSBFP)		Completed Dozer Line, Completed - Inspected
	Summits		Completed Dozer Line, Completed - Ready for Inspection
	Camp		Completed Dozer Line, No Repair Needed
	Clean Up Area		Completed Dozer Line, Other - See Comments
	Closure		Completed Dozer Line, Repair Needed
	Culvert		Completed Hand Line, Completed - Inspected
	Dip Site		Completed Hand Line, No Repair Needed
	Drop Point		Completed Hand Line, Repair Needed
	Dozer Push		Road as Completed Line, Completed - Inspected
	Fence - Cut/Damaged		Road as Completed Line, No Repair Needed
	Remote Sleeping Area		Road as Completed Line, Repair Needed
	Gate		Dolan Repair Area
	Mining Hazard		Restricted Area
	Hazard Tree		CA State Park
	Unimproved Landing Area		Ventana Wilderness
	Helispot		The Pacific Ocean
	Hot Spot		Wildfire Daily Fire Perimeter
	Incident Command Post		Trail
	Internet Access		Expressway
	Repair Point		Secondary Hwy
	Repeater		Local Connector
	Road Repair		Local Road
	Safety Zone		Ramp
	Sling Site		4WD
	Staging Area		Tunnel
	Structure Wrap		Forest Service
	Water Source		Fort Hunter Liggett
	Water Development or Draft Site		Township/Range
	Value at Risk		Section
	Unknown		Federal Responsibility Area
	Unknown		Local Responsibility Area
	Unknown		State Responsibility Area
	Unknown		Runway
	Repair Needed		
	Unknown		
	Access or Improved Road, Completed - Inspected		
	Access or Improved Road, No Repair Needed		
	Access or Improved Road, Repair Needed		

