




Suppression Repair

Dolan Fire
 CA-LPF-002428
 11/4/2020 DAY

124,924 acres at 9/28/2020 2000 hrs

- | | | | |
|--|--|--|--|
| | Microsoft Building Footprints (MSBFP) | | Completed Dozer Line, Completed - Ready for Inspection |
| | Summits | | Completed Dozer Line, No Repair Needed |
| | Camp | | Completed Dozer Line, Other - See Comments |
| | Closure | | Completed Dozer Line, Repair Needed |
| | Culvert | | Completed Hand Line, Completed - Inspected |
| | Dip Site | | Completed Hand Line, No Repair Needed |
| | Drop Point | | Completed Hand Line, Repair Needed |
| | Dozer Push | | Road as Completed Line, Completed - Inspected |
| | Fence - Cut/Damaged | | Road as Completed Line, No Repair Needed |
| | Remote Sleeping Area | | Road as Completed Line, Repair Needed |
| | Gate | | Dolan Repair Area |
| | Mining Hazard | | Restricted Area |
| | Hazard Tree | | CA State Park |
| | Unimproved Landing Area | | Ventana Wilderness |
| | Helispot | | The Pacific Ocean |
| | Hot Spot | | Wildfire Daily Fire Perimeter |
| | Incident Command Post | | Trail |
| | Internet Access | | Expressway |
| | Repair Point | | Secondary Hwy |
| | Repeater | | Local Connector |
| | Road Repair | | Local Road |
| | Safety Zone | | Ramp |
| | Sling Site | | 4WD |
| | Staging Area | | Tunnel |
| | Structure Wrap | | Forest Service |
| | Water Source | | Fort Hunter Liggett |
| | Value at Risk | | Local Responsibility Area |
| | Unknown | | State Responsibility Area |
| | Division Break | | Township/Range |
| | Repair Needed | | Land Grant |
| | Unknown | | Section |
| | Access or Improved Road, Completed - Inspected | | Federal Responsibility Area |
| | Access or Improved Road, No Repair Needed | | Local Responsibility Area |
| | Access or Improved Road, Repair Needed | | State Responsibility Area |
| | Completed Dozer Line, Completed - Inspected | | Runway |



EAIMT GISS
 11/3/2020 2141
 Acres from IR and field reports
 NAD 1983 California Teale Albers

