



Suppression Repair
 Tamarack
 NW-HTF 0030419
 7/30/2021
 68,896 acres
 as of 7/29/2021, 1322 Hrs



<ul style="list-style-type: none"> Ops Completed Completed Doser Line Completed Hand Line Fire Perimeter Fire Edge Contained Line Air Operations Drop Site 	<ul style="list-style-type: none"> Assignment Breaks Division Break Branch Break Logistics Drop Point Closure Camp 	<ul style="list-style-type: none"> Reference Value at Risk Fire Station Bridge 	<ul style="list-style-type: none"> Repair Road Repair Resource Location Repair Point Hazard Tree Fence - Cut/Damaged Dozer Push Culvert 	<ul style="list-style-type: none"> Clean Up Area Communications Mobile Weather Unit Internet Access Repeater Water Water Source Restricted Water Source 	<ul style="list-style-type: none"> Wilderness Wilderness Study Areas Structures Trail Trail - Nat Rec/Scenic/Historic ADMIN AGENCY BIA BLM ST Road - Light Duty - Unspecified Composition Road - Light Duty - Unimproved Highway Highway w/Median Parking Road - Light Duty - Dirt Road - Light Duty - Gravel Road - Light Duty - Paved 	<ul style="list-style-type: none"> UND; PVT USBR USFS Unknown Completed - Inspected Reason Needed Completed - Ready for Inspection No Repair Needed Other - See Comments Unknown 	<ul style="list-style-type: none"> Other - See Comments Unknown Completed - Inspected Reason Needed Completed - Ready for Inspection No Repair Needed Other - See Comments Unknown
--	---	--	---	---	--	--	--

0 0.6 1.2 Miles

1:50,000
 IAD 1983 UTM Zone 11N
 Avion from Base 1983
 10/20/2017 2:07 PM
 suppression_repair_2021_tamarack_IVHTF0030419