



North Harvey and Harvey Creek Rds

- Close gate on 1935030 rd and improve natural barrier to discourage access to grizzly bear habitat.
- 1935030 Rd needs to be graded (Grader and two water tenders).
- Repair surface of 4 asphalt topped bridges on Harvey Creek Rd USFS 1935000. Surface is gouged and patches of approaches are crumbled and needs to be replaced.
- Harvey Creek Rd USFS 1935000 needs to be graded (Grader and two water tenders).



Repair Needed	In Progress, Completed - Ready for Inspection	Completed - Inspected	Other/Not Needed	Repair Lines	Fire Lines
Close Road	Close Road	Close Road	Close Road	Repair Needed	Completed Line
Culvert	Culvert	Culvert	Culvert	In Progress, Completed - Ready for Inspection	Completed Dozer Line
Pump Site	Pump Site	Pump Site	Pump Site	Completed - Inspected	Completed Hand Line
Water	Water	Water	Water	Other/Not Needed	R - Road as Completed Line
Crossing/Riparian Damage	Crossing/Riparian Damage	Crossing/Riparian Damage	Crossing/Riparian Damage		Line Break Completed
Other	Other	Other	Other		