




DIV T

DIV U



Suppression Repair Map Overview
NORTH KLAMATHON INCIDENT
 OR-MED-268
Final

- Completed - Inspected
- Repair Needed
- Completed - Ready for Inspection
- Unknown
- In Progress
- No Repair Needed

North Klamathon
 Suppression Repair
 PNLYL8 (1502)
 OR-MED-268
 Oct 3, 2018
 NAD83
 1:22,410