


Div P - Point Repair Status



UniqueID	RepairStatus	RepairComments
P025	Unknown	Ask local timber dept. what they want done. 9/16/18 DM No repair needed.
P027	No Repair Needed	Remove tanksX2, all gear, and garbage
P028	Repair Needed	Remove tanks, gear, and flagging. Seed nearby staging area after pulling in pushed woody debris and spreading over dug soil.
P029	Repair Needed	Felling operations snag dropped across trailhead. Needs bucked stack and slash chipped/disposed of
P030	Repair Needed	Remove hose after use
P031	Repair Needed	If hose lay and sprinklers installed, remove and rip down flagging
P056	Completed - Inspected	If hose lay and pump installed remove both. Remove flagging.
P057	Repair Needed	Basic spot checks, keep petrol out of water
P058	Repair Needed	Mix of chipping and even dispersion. Rehab of soil and landing footprint.
P059	Other - See Comments	
P060	Other - See Comments	
P064	Repair Needed	Trailhead board, permit box, and Wilderness boundary sign were all taken down and need reinstated. Saddle trail sign needs new post near 1993 rd. and sign reinstated
P068	Repair Needed	French Pete Trailhead board and Wilderness boundary sign were removed and replaced with closure notice and flagging
P069	Other - See Comments	
P070	Repair Needed	Remove flagging and reinstall board and sign.
P071	Repair Needed	Pull pump, hose, all gear and trash
P072	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P076	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P077	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P078	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P081	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P084	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P088	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P093	No Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P131	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P132	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P133	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P134	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P135	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P136	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.
P141	Other - See Comments	
P145	Repair Needed	Remove slash and rounds from roadway. Disperse evenly via chipping or transport.

Terwilliger
OR-WIF-180227

Fire perimeter as of
09/27/2018, 2027 hrs
11,445 acres

Updated:
Sep 30, 2018
@ 1534

- | | | | | |
|------------------------------------|-------------------------|------------------|----------------------------------|---------------------|
| Repair Status | ▲ Impassable Road | Ⓟ Pump | — Completed Line | ▫ Private Ownership |
| ● Completed - Inspected | ✕ Closure | Ⓢ Water Source | ⋯ Completed Dozer Line | ▫ US Forest Service |
| ● Completed - Ready for Inspection | ◆ Dip Site | Ⓣ Water Tank | - - - Completed Hand Line | ▫ Wilderness |
| ● In Progress | ● Drop Point | ⚠ Value at Risk | R - R - R Road as Completed Line | |
| ● No Repair Needed | Ⓜ Helibase |) Division Break | ⋯ Arterial Road | |
| ● Other - See Comments | Ⓜ Helispot | | ⋯ Collector Road | |
| ● Unknown | Ⓜ Incident Command Post | | ⋯ Local Road | |
| ● Repair Needed | | | ⋯ Powerlines | |
| | | | ⋯ State Highway | |

0 0.5 1 2 Miles

NAD83 UTM10N