

# Suppression Repair

Beachie Creek  
ORWIF-200299  
Riverside 3  
ORMHF-000859  
10/04/20  
Page: 3


- Repair Point Status**
- Repair Needed
  - No Repair Needed
  - Unknown
- Repair Line Status**
- Repair Needed
  - Unknown
  - Bridge
  - Drop Point
  - Dozer Push
  - Fire Station
  - Repeater
  - Water Source
- FC Point Type**
- X Division Break
  - Contained Line
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Access or Improved Road
  - Line Break Completed
  - Aerial Hazard
  - Uncontrolled Fire Edge
  - Wildfire Daily Fire Perimeter
  - Fire Station
  - State Highway
  - County Road
- Intermediate road**
- Minor road**
- Decommissioned or Closed**
- Rivers and Streams**
- Lake, Pond or Reservoir**
- County Boundary**
- Ranger District Boundaries**
- Forest Service Wilderness Area**
- Bureau of Land Management**
- U.S. Forest Service**
- State**
- Local Government**
- Private/Unknown**

FC Point Type	Repair Status	Repair Comments	Label
Bridge	Repair Needed		Bridge Out
Bridge	Repair Needed		Bridge Out
Dozer Push	Repair Needed		
Dozer Push	Repair Needed		
Drop Point	No Repair Needed	Road turnout, no repair needed. REAF BERNARDS	DP-11
Drop Point	No Repair Needed		DP-12
Drop Point	No Repair Needed	No repairs, REAF BERNARDS	DP-13
Drop Point	Repair Needed		DP-10
Drop Point	Repair Needed		DP-15
Drop Point	Repair Needed		DP-2
Drop Point	Repair Needed		DP-30
Drop Point	Repair Needed		DP-4
Drop Point	Repair Needed		DP-6
Drop Point	Repair Needed		DP-7
Drop Point	Repair Needed		DP-80
Drop Point	Repair Needed		DP-83
Drop Point	Repair Needed		DP-83

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	Repair Needed		DP-84
Drop Point	Repair Needed		DP-86
Drop Point	Repair Needed		DP-89
Drop Point	Repair Needed		DP-9
Drop Point	Repair Needed		DP-94
Drop Point	Repair Needed		DP-95
Drop Point	Repair Needed		DP-96
Drop Point	Repair Needed		DP-97
Drop Point	Repair Needed		DP-98
Drop Point	Repair Needed		DP-99
Repeater	Repair Needed		CHD 9
Water Source	Repair Needed		
Water Source	Repair Needed		
Water Source	Repair Needed		
Water Source	Repair Needed		
Water Source	Unknown		

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		125
Road as Completed Line	Unknown		194
Road as Completed Line	Unknown		215
Road as Completed Line	Unknown		245
Road as Completed Line	Unknown		298
Road as Completed Line	Unknown		493
Road as Completed Line	Unknown		519
Road as Completed Line	Unknown		582
Road as Completed Line	Unknown		705
Road as Completed Line	Unknown		797
Road as Completed Line	Unknown		729
Road as Completed Line	Unknown		747
Road as Completed Line	Unknown		838
Road as Completed Line	Unknown		851
Road as Completed Line	Unknown		851
Road as Completed Line	Unknown		1048
Road as Completed Line	Unknown		1110
Road as Completed Line	Unknown		1144
Road as Completed Line	Unknown		1208
Road as Completed Line	Unknown		1372
Road as Completed Line	Unknown		1469
Road as Completed Line	Unknown		1495
Road as Completed Line	Unknown		1529
Road as Completed Line	Unknown		2072
Road as Completed Line	Unknown		2256
Road as Completed Line	Unknown		2563
Road as Completed Line	Unknown		5873
Road as Completed Line	Unknown		6005
Road as Completed Line	Unknown		28687
Road as Completed Line	Repair Needed	pull berms, waterbars, block atv access	1180
Road as Completed Line	Repair Needed		2059
Road as Completed Line	Repair Needed		2781
Road as Completed Line	Repair Needed		2993
Road as Completed Line	Repair Needed		3122
Road as Completed Line	Repair Needed	chip wind row of slash on green side of road	3262
Proposed Dozer Line	Unknown		9306
Line Break Completed	Repair Needed		343
Completed Hand Line	Unknown		185
Completed Hand Line	Unknown		311
Completed Hand Line	Unknown		657
Completed Hand Line	Unknown		662
Completed Hand Line	Unknown		712
Completed Hand Line	Unknown		901
Completed Hand Line	Unknown		928
Completed Hand Line	Unknown		940
Completed Hand Line	Unknown		991
Completed Hand Line	Unknown		1156
Completed Hand Line	Unknown		1264
Completed Hand Line	Unknown		1460
Completed Hand Line	Unknown		2066
Completed Hand Line	Unknown		2294
Completed Hand Line	Unknown		2782
Completed Hand Line	Unknown		9975
Completed Hand Line	Repair Needed	minimal waterbars needed on steep portions near bottom	358
Completed Hand Line	Repair Needed		596
Completed Hand Line	Repair Needed		866
Completed Hand Line	Repair Needed		1026
Completed Hand Line	Repair Needed	Line is a mix of saw line/cold trail and handline w/ sap benches. Will need repair. TRICK HULL	1186
Completed Hand Line	Repair Needed	A mix of Existing trail, hand line, and cold trail.	1301
Completed Hand Line	Repair Needed		2098
Completed Hand Line	Repair Needed		2777
Completed Hand Line	Repair Needed		2923
Completed Hand Line	Repair Needed		3602
Completed Hand Line	Repair Needed		5879
Completed Hand Line	Repair Needed		13137
Completed Dozer Line	Unknown		128

FC Line Type	Repair Status	Repair Comments	Length Feet
Completed Dozer Line	Unknown		134
Completed Dozer Line	Unknown		380
Completed Dozer Line	Unknown		403
Completed Dozer Line	Unknown		408
Completed Dozer Line	Unknown		434
Completed Dozer Line	Unknown		453
Completed Dozer Line	Unknown		459
Completed Dozer Line	Unknown		520
Completed Dozer Line	Unknown	Only 100' of dozer line on west end. The rest is just brushed out by hand.	533
Completed Dozer Line	Unknown		533
Completed Dozer Line	Unknown		546
Completed Dozer Line	Unknown		631
Completed Dozer Line	Unknown		635
Completed Dozer Line	Unknown		646
Completed Dozer Line	Unknown		660
Completed Dozer Line	Unknown		700
Completed Dozer Line	Unknown		724
Completed Dozer Line	Unknown		761
Completed Dozer Line	Unknown		765
Completed Dozer Line	Unknown		865
Completed Dozer Line	Unknown		942
Completed Dozer Line	Unknown		955
Completed Dozer Line	Unknown		1052
Completed Dozer Line	Unknown		1071
Completed Dozer Line	Unknown		1137
Completed Dozer Line	Unknown		1137
Completed Dozer Line	Unknown		1153
Completed Dozer Line	Unknown		1175
Completed Dozer Line	Unknown		1180
Completed Dozer Line	Unknown		1209
Completed Dozer Line	Unknown		1993
Completed Dozer Line	Unknown		1535
Completed Dozer Line	Unknown		1668
Completed Dozer Line	Unknown		1750
Completed Dozer Line	Unknown		1980
Completed Dozer Line	Unknown		1993
Completed Dozer Line	Unknown		2030
Completed Dozer Line	Unknown		2039
Completed Dozer Line	Unknown	non inc. Personnel installed	2194
Completed Dozer Line	Unknown		2440
Completed Dozer Line	Unknown		2443
Completed Dozer Line	Unknown		2502
Completed Dozer Line	Unknown		2544
Completed Dozer Line	Unknown		2634
Completed Dozer Line	Unknown		2929
Completed Dozer Line	Unknown		2993
Completed Dozer Line	Unknown		3243
Completed Dozer Line	Unknown		3243
Completed Dozer Line	Unknown		3812
Completed Dozer Line	Unknown		4676
Completed Dozer Line	Unknown		4678
Completed Dozer Line	Unknown		4741
Completed Dozer Line	Unknown		6100
Completed Dozer Line	Unknown		7532
Completed Dozer Line	Unknown		8018
Completed Dozer Line	Unknown		1223
Completed Dozer Line	Unknown		19943
Completed Dozer Line	Repair Needed	standard suppression repair for federal land	78
Completed Dozer Line	Repair Needed		100
Completed Dozer Line	Repair Needed	Access needs blocked	335
Completed Dozer Line	Repair Needed	pull berms, waterbars, scatter slash, block atv access	354
Completed Dozer Line	Repair Needed		471
Completed Dozer Line	Repair Needed	pull berms, waterbars, scatter slash, block atv access	633
Completed Dozer Line	Repair Needed	pull berms, waterbars, scatter slash, block atv access	775
Completed Dozer Line	Repair Needed	berms and waterbars pull slash	978
Completed Dozer Line	Repair Needed		995
Completed Dozer Line	Repair Needed	pull berms and waterbars, block road at each end, collapse logs on private portion. ARCH cleared by B Saunter	916
Completed Dozer Line	Repair Needed	Flat ground. No water bars needed. Access needs blocked.	946
Completed Dozer Line	Repair Needed		1034
Completed Dozer Line	Repair Needed		1232



0 0.5 1 2 Miles

1:33,000 - 10/3/2020 2053  
Acres from GIS  
North American 1983 Datum, LatLong Grid