

Suppression Repair

Beachie Creek
ORWIF-200299

Riverside
ORMHF-000859

10/13/20
Page: 13

- City, Town, or Community
- Unknown
- ▬ County Boundary
- Repair Needed
- No Repair Needed
- Fire Station
- Law Enforcement
- ▲ Structures
- ▲ Completed Dozer Line
- ▲ Completed Hand Line
- ▲ Road as Completed Line
- ▲ Access or Improved Road
- ▲ Proposed Dozer Line
- ▲ Planned Fire Line
- ▲ Planned Secondary Line
- Other
- Completed - Inspected
- Completed - Ready for Inspection
- ▬ Airstrip
- ▬ Railroad
- ▬ State Highway
- ▬ County Road
- ▬ Intermediate road
- ▬ Minor road
- ▬ Decommissioned or Closed
- ▬ BPA Transmission Lines
- ▬ Wildfire Daily Fire Perimeter
- ▬ City Limits
- ▬ Ranger District Boundaries
- ▬ Bureau of Land Management
- ▬ U.S. Forest Service
- ▬ Other Federal
- ▬ State
- ▬ Local Government
- ▬ Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	No Repair Needed		DP-70
Drop Point	Repair Needed		DP-55
Drop Point	Repair Needed		DP-66
Drop Point	Repair Needed		DP-67
Drop Point	Repair Needed	Pick up trash, remove toilets/hand wash stations	DP-77
Drop Point	Repair Needed		DP-95
Drop Point	Unknown		DP-63
Drop Point	Unknown		DP-68
Drop Point	Unknown		DP-69
Drop Point	Unknown		DP-75
Drop Point	Unknown		DP-76
Drop Point	Unknown		DP-92
Drop Point	Unknown		DP-94
Helibase	Unknown		Davis Strip
Value at Risk	Unknown	Consult READs before snagging	Sensitive Area

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		729
Road as Completed Line	Unknown		791
Road as Completed Line	Unknown		1966
Road as Completed Line	Unknown		2543
Road as Completed Line	Unknown		2969
Road as Completed Line	Repair Needed	Replace boulders to close road at Junction with Rock Creek Road	1188
Road as Completed Line	Completed - Inspected		562
Road as Completed Line	Completed - Inspected		962
Road as Completed Line	Completed - Inspected		1474
Road as Completed Line	Completed - Inspected	No repair needed.	2081
Road as Completed Line	Completed - Inspected		4758
Road as Completed Line	Completed - Inspected		5993
Proposed Dozer Line	Other - See Comments	Need to pick up wood from feller buncher work	4379
Planned Secondary Line	Other - See Comments	Pick up wood from feller buncher work and grade road	3729
Planned Secondary Line	Other - See Comments	Pick up wood from feller buncher work and grade road	4433
Planned Secondary Line	Other - See Comments	Needs wood picked up from feller buncher operation. Grade Tom Rock Road.	15057
Planned Secondary Line	Other - See Comments	Pick up piles from feller buncher work and grade road.	15267
Planned Secondary Line	Other - See Comments	Pick up wood from feller buncher work and grade road.	28700
Planned Fire Line	Unknown		854
Planned Fire Line	Unknown		2987
Planned Fire Line	Completed - Inspected		2482
Other	Unknown		529
Other	Unknown		3315
Completed Hand Line	Unknown		319
Completed Hand Line	Unknown		354
Completed Hand Line	Unknown		453
Completed Hand Line	Unknown		588
Completed Hand Line	Unknown		2063
Completed Hand Line	Unknown		2174
Completed Hand Line	Unknown	Standards will be addressed in DM's rehab specs.	2921
Completed Hand Line	Unknown		7293
Completed Hand Line	Unknown	Will be addressed per repair turnaround specs.	29129
Completed Hand Line	Completed - Inspected		133

FC Line Type	Repair Status	Repair Comments	Length Feet
Completed Hand Line	Completed - Inspected	Flip berm in, add water bars and slash	237
Completed Hand Line	Completed - Inspected		238
Completed Hand Line	Completed - Inspected		374
Completed Hand Line	Completed - Inspected	Pull slash across line, flip berms	671
Completed Hand Line	Completed - Inspected		942
Completed Hand Line	Completed - Inspected	Pull in berm several water bars needed and pull in slash	1222
Completed Hand Line	Completed - Inspected	Inspected meets standards. B McCarrill	1820
Completed Hand Line	Completed - Inspected	Gentle slopes. Needs berms and slash pulled in.	2062
Completed Hand Line	Completed - Inspected	Crew pulled in berm and slash. Repairs complete.	3640
Completed Dozer Line	Unknown		317
Completed Dozer Line	Unknown		3563
Completed Dozer Line	Completed - Ready for Inspection	Flip berm in, add water bars and slash*** completed per repair specs	498
Completed Dozer Line	Completed - Ready for Inspection	Completed to specs in repair plan	668
Completed Dozer Line	Completed - Ready for Inspection	Repair meets standards outlined in repair plan	787
Completed Dozer Line	Completed - Ready for Inspection	Flip berm in, add water bars and slash*** completed per repair specs	918
Completed Dozer Line	Completed - Ready for Inspection	Meets repair specs	1266
Completed Dozer Line	Completed - Ready for Inspection	Required to standards in repair plan	1680
Completed Dozer Line	Completed - Ready for Inspection	Meets repair specs	2421
Completed Dozer Line	Completed - Ready for Inspection	Meets repair specs	2423
Completed Dozer Line	Completed - Ready for Inspection	Meets repair specs	3092
Completed Dozer Line	Completed - Ready for Inspection	Repair completed to specs given in the fire suppression repair plan for beachie creek fire.	3117
Completed Dozer Line	Completed - Inspected	Berm pulled in and sufficient slash added. Surface scarified. Could benefit from seeding. No effective water bars found. However subsoiling was frequent and grade was gentle enough that completed work could be adequate if also seeded.*** meets specs in repair plan	302
Completed Dozer Line	Completed - Inspected	Flopped berm, water bar, and covered with slash	1098
Completed Dozer Line	Completed - Inspected	Repair completed for piece of dozer line, per specs outlined in fire suppression repair plan for the beachie creek fire. *Repairs consistent with fire suppression repair plan specs. B McCarrill	2222
Access or Improved Road	Unknown		1512
Access or Improved Road	Unknown		3518
Access or Improved Road	Unknown		5587
Access or Improved Road	Unknown		7177
Access or Improved Road	Unknown		10538
Access or Improved Road	Unknown		39988
Access or Improved Road	Unknown		31214
Access or Improved Road	Unknown		37167
Access or Improved Road	Completed - Inspected		3039

