

Suppression Repair

Beachie Creek
ORWIF-200299
Beachie 4

Riverside
ORMHF-000859
10/08/20
Page: 11

- Repair Point Status**
- Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown
- Repair Line Status**
- Completed - Inspected
 - Completed - Ready for Inspection
 - Repair Needed
 - Other - See Comments
 - Unknown
 - Drop Point
 - Gate
 - Repeater
 - Stream Crossing
 - Water Source
 - Water Development or Draft Site
- Value at Risk**
- Division Break
 - Contained Line
 - Completed Dozer Line
 - Decommissioned Hand Line
 - Road as Completed Line
 - Access or Improved Road
 - Line Break Completed
 - Planned Fire Line
 - Planned Secondary Line
 - Aerial Hazard
 - Uncontrolled Fire Edge
 - BPA Transmission Lines
 - Wildfire Daily Fire Perimeter
- Other Symbols**
- County Road
 - Major road
 - Intermediate road
 - Minor road
 - Decommissioned or Closed
 - Rivers and Streams
 - Lake, Pond or Reservoir
 - County Boundary
 - Ranger District Boundaries
 - BLM Wilderness Area
 - Forest Service Wilderness Area
 - Bureau of Land Management
 - U.S. Forest Service
 - State
 - Private/Unknown

| FC Point Type | Repair Status | Repair Comments | Label |
|---------------|---------------|--|-------|
| Drop Point | Repair Needed | Richardson- 0.25 acre of disturbed compacted bare soil. Seed, straw, cover with slash. Possible decompat with excavator if available | DP-48 |
| Drop Point | Repair Needed | | DP-79 |
| Drop Point | Repair Needed | | DP-81 |
| Drop Point | Unknown | | DP-31 |
| Drop Point | Unknown | | DP-33 |
| Drop Point | Unknown | | DP-35 |
| Drop Point | Unknown | | DP-36 |
| Drop Point | Unknown | | DP-46 |
| Drop Point | Unknown | | DP-47 |
| Drop Point | Unknown | | DP-49 |
| Drop Point | Unknown | | DP-50 |
| Drop Point | Unknown | | DP-51 |
| Drop Point | Unknown | | DP-52 |

| FC Point Type | Repair Status | Repair Comments | Label |
|---------------------------------|----------------------|-----------------|----------------|
| Drop Point | Unknown | | DP-53 |
| Drop Point | Unknown | | DP-78 |
| Gate | No Repair Needed | | |
| Repeater | Unknown | | CMD-10 |
| Repeater | Unknown | | CMD-11 |
| Value at Risk | Other - See Comments | | Sensitive Area |
| Water Development or Draft Site | No Repair Needed | | |
| Water Development or Draft Site | Unknown | | |
| Water Source | Repair Needed | | |
| Water Source | Unknown | | |

| FC Line Type | Repair Status | Repair Comments | Length Feet |
|------------------------|----------------------------------|---|-------------|
| Road as Completed Line | Unknown | | 716 |
| Road as Completed Line | Unknown | | 1165 |
| Road as Completed Line | Unknown | | 1642 |
| Road as Completed Line | Unknown | | 2535 |
| Road as Completed Line | Unknown | | 6619 |
| Road as Completed Line | Repair Needed | | 15301 |
| Road as Completed Line | Other - See Comments | consult landowner | 3781 |
| Planned Secondary Line | Unknown | | 9321 |
| Planned Dozer Line | Unknown | | 12476 |
| Planned Fire Line | Repair Needed | | 9946 |
| Planned Fire Line | Repair Needed | | 18949 |
| Other | Unknown | Determine if this was put up for fire or flagged for another non fire reason. If fire related pull flagging. | 362 |
| Other | Unknown | | 642 |
| Completed Hand Line | Unknown | | 3184 |
| Completed Hand Line | Unknown | | 4668 |
| Completed Hand Line | Repair Needed | repair per local unit specs | 204 |
| Completed Hand Line | Repair Needed | Obliterate berms, scatter slash back over line. Marshy area | 613 |
| Completed Hand Line | Completed - Ready for Inspection | | 3096 |
| Completed Hand Line | Completed - Ready for Inspection | Repair per local specs, water bars, obliterate berms, scatter slash over line | 1303 |
| Completed Hand Line | Completed - Ready for Inspection | Needs waterbars, some steep segments, scatter available slash, scatter slash where handline meets perennial stream, clear any debris at inlet of culvert at end of handline | 4172 |
| Completed Dozer Line | Unknown | | |
| Completed Dozer Line | Unknown | | 3802 |
| Completed Dozer Line | Repair Needed | Repair per local unit specs | |
| Completed Dozer Line | Repair Needed | Repair per local unit specs | |
| Completed Dozer Line | Repair Needed | Repair per local BLM specs, obliterate berms and push piles, water bar as needed, needs medium excavator with grapple claw, access through private land to south | |
| Completed Dozer Line | Repair Needed | | |

| FC Line Type | Repair Status | Repair Comments | Length Feet |
|-------------------------|----------------------------------|---|-------------|
| Completed Dozer Line | Repair Needed | Discuss existing road with land owner if possible. | |
| Completed Dozer Line | Repair Needed | consult landowner, likely needs medium excavator | |
| Completed Dozer Line | Repair Needed | obliterate berms, need medium excavator with grapple bucket | |
| Completed Dozer Line | Repair Needed | repair per local unit specs | 24 |
| Completed Dozer Line | Repair Needed | Drag slash back over line | 218 |
| Completed Dozer Line | Repair Needed | consult with landowner | 290 |
| Completed Dozer Line | Repair Needed | Consult with landowner | 311 |
| Completed Dozer Line | Repair Needed | Replace logs to block access. McCantion | 432 |
| Completed Dozer Line | Repair Needed | Repair to specs. Might not need any work | 460 |
| Completed Dozer Line | Repair Needed | A few wet areas | 801 |
| Completed Dozer Line | Repair Needed | Repair per local specs, obliterate berms and push piles, scatter slash back on line, consult reeds on marshy area | 882 |
| Completed Dozer Line | Repair Needed | Repair to specs. A few wet areas. | 1103 |
| Completed Dozer Line | Repair Needed | Repair per local specs, obliterate berms, obliterate push piles, scatter slash over line | 2174 |
| Completed Dozer Line | Repair Needed | Need free mulch (can use vegetation nearby) conduct repair to specs of repair plan. | 2634 |
| Completed Dozer Line | Repair Needed | Repair per local specs, water bars, obliterate berms, scatter slash over line | 3427 |
| Completed Dozer Line | Repair Needed | some larger dozer pushouts, sections of berms 2-3' tall, sections of steep line will need water bars, recommend to use available slash to cover dozer line, one hand line comes off dozer line approx 500' from the end | 4307 |
| Completed Dozer Line | Repair Needed | Repair to dozer repair plan specifications. | 5431 |
| Completed Dozer Line | Repair Needed | water bars as needed, obliterate berms and dozer pushes | 506 |
| Completed Dozer Line | Completed - Ready for Inspection | Unsure what can be done. The line follows a road bed cut through a hill. Any outflow will end up in a rock quarry. | 12347 |
| Access or Improved Road | Unknown | | 1431 |
| Access or Improved Road | Unknown | | 3168 |
| Access or Improved Road | Unknown | | 7903 |
| Access or Improved Road | Unknown | | 9672 |
| Access or Improved Road | Repair Needed | Repair to specs. Block access? | |
| Access or Improved Road | Repair Needed | Ditches need cleaned | 1854 |

