

Suppression Repair

Beachie Creek
ORWIF-200299

Riverside
ORMHF-000859

10/18/2020



Repair points (located on BLM & USFWS) only

Incident Name	FC Point Type	Label	Comments	Repair Status	Repair Comments	LND_MGR
Beachie Creek	Culvert			Other - See Comments	BAER alert- melted culvert, non live stream	USFS
Beachie Creek	Culvert			Other - See Comments	BAER alert- melted culvert, non live stream	USFS
Beachie Creek	Culvert		Culvert filling up from erosion on bank above.	Repair Needed		USFS
Beachie Creek	Culvert		Melted plastic culvert	Other - See Comments	BAER ALERT - FSR 2223, MP 4.32, remove and replace with 34' x 24" culvert.	USFS
Beachie Creek	Culvert		Melted plastic culvert	Repair Needed	BAER ALERT - FSR 2223-520, MP 10.79 (from hwy 22), remove and replace with 32' x 24" culvert.	USFS
Beachie Creek	Culvert		Melted plastic Culvert	Repair Needed	BAER ALERT - FSR 2223-520, MP 11.21 (from hwy 22), remove and replace with 32' x 24" culvert.	USFS
Beachie Creek	Drop Point	DP-48	Parking area	Repair Needed	Richardson- 0.25 acre of disturbed compacted bare soil. Seed, straw, cover with slash. Possible decompress with excavator if available	BLM
Beachie Creek	Hazard		Rick face crumbling into road large rocks falling	Repair Needed	Scaling? Excavator?	USFS
Beachie Creek	Lookout		Cut p-line and flagged 2/10 of mile to lookout point.	Repair Needed		USFS
Beachie Creek	Other		Question to ODOT about felling trees	Other - See Comments		USFS
Beachie Creek	Other			Other - See Comments	BAER alert- burned campground sign	BLM
Beachie Creek	Other		Retaining log burnt out on road. Road failing and cracking.	Repair Needed		USFS

Repair lines (located on BLM & USFWS) only

Incident Name	FC Line Type	Label	Comments	Repair Status	Repair Comments	LND_MGR	Length Feet
Beachie Creek	Completed Dozer Line		Show as perimeter	Completed - Ready for Inspection	Unsure what can be done. The line follows a road bed cut through a hill. Any outflow will end up in a rock quarry.	BLM	506
Beachie Creek	Completed Hand Line		Direct hand line on fires edge	Completed - Ready for Inspection		BLM	613
Beachie Creek	Completed Hand Line		Direct Handline on fires edge. Some heat near where P-line comes in. Above and below that junction. Could use a squad or two to check with bladder bag. (perim edited KG 20200923 1800)	Completed - Ready for Inspection		BLM	3184
Beachie Creek	Planned Secondary Line		Upper Molalla Rd or Corridor Rd	Other - See Comments	Utilize Molalla River for primary holding feature. Difficult to back fir off the river or road. Helitorch is suggested method. Road is in excellent condition, paved and accessible by any vehicle. Good ingress and egress	BLM	27113
Beachie Creek	Road as Completed Line		old road, not a good line, there is no canopy break, BLM	Other - See Comments	reclose or decommission?	BLM	989
Beachie Creek	Road as Completed Line		may have been old road, used as trail, reopened with dozer scrape, fire appears to have been north of this road. *Small berm. Line is still hardened by previous use as road. *Recommendation-Pull in berm and brush in dozer line b	Other - See Comments	repair per local unit specs, consult BLM trails	BLM	2492
Beachie Creek	Completed Dozer Line		L.Blandchard	Repair Needed	Repair per local specs, needs a few water bars on slopes, obliterate berms and push piles, scatter slash on line. Consult local landowner for line off BLM land. Note: Dozer line on private ground is okay as is. No repair required. However the fence line is cut and will need repaired at the BLM/private property line. Jake Goebel E-279	BLM	3470
Beachie Creek	Other		P-line to lookout point. Cut brush/small trees and flagged line. Vegetation loss to 18" wide tread.	Repair Needed	Cover with brush. Pull flagging	USFS	1046
Beachie Creek	Planned Fire Line		Road needs to be opened a little. Some some stump holes along the road. Table rock trailhead road.	Repair Needed		BLM	18840
Beachie Creek	Completed Dozer Line		JNez REAF ARCH	Repair Needed	Repair per local specs, water bars, obliterate berms, scatter slash over line 10/13 Theve and Garcia, repair still needed, but landing seeded	BLM	2634
Beachie Creek	Completed Dozer Line			Repair Needed	some larger dozer pushouts, sections of berms 2-3' tall, sections of steep line will need water bars. recommend to use available slash to cover dozer line. one hand line comes off dozer line approx 500' from the end, 10/13 Theve and Garcia still needs repair	BLM	3427
Beachie Creek	Completed Dozer Line			Repair Needed	Replace logs to block access. MScanlon; 10/17 still needs blocked	BLM	311
Beachie Creek	Completed Dozer Line		BLM and state lands, repair per local unit specs. width varies	Repair Needed	water bars as needed, obliterate berms and dozer pushes; 10/15 Theve and Garcia confirms needs work, possibly block roads, seed stream crossing	BLM	5431
Beachie Creek	Access or Improved Road			Repair Needed	Ditches need cleaned	BLM	1854
Beachie Creek	Completed Dozer Line		CPI road bull dozed open. Road seems to be on existing road.	Repair Needed	Waterbar as appropriate and seed roads, cut banks and entrances off of Hwy 22. Approximately 15 water bars will be needed. Recommend mini or medium sized excavator. Trash left behind by CPI including old telephone poles, insulators, wire, beverage bottles, food wrappers, etc.	USFS	1747
Beachie Creek	Completed Hand Line			Repair Needed	obliterate berms, scatter slash over line	BLM	32
Beachie Creek	Completed Hand Line		discontinues handline	Repair Needed	obliterate berm, scatter slash over line	BLM	128
Beachie Creek	Completed Dozer Line			Repair Needed	Light to medium excavator with grapple bucket	BLM	404
Beachie Creek	Completed Dozer Line		Dozer along unknown trail corridor, consult BLM trail read	Repair Needed	medium excavator with grapple bucket	BLM	373
Beachie Creek	Completed Dozer Line			Repair Needed	Light to medium excavator, remove berms and scatter slash	BLM	646
Beachie Creek	Completed Dozer Line		Dozer line to river, needs repair	Repair Needed		BLM	166
Beachie Creek	Road as Completed Line	2223	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	21283
Beachie Creek	Road as Completed Line	2223	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	20946
Beachie Creek	Road as Completed Line	520	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	19098
Beachie Creek	Road as Completed Line	525	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	1861