

Label	FC Point Type	Repair Status	Repair Comments
47863	Landing or Log Deck	Repair Needed	Piles remain will need to be picked up. 8/31/21 PardueREAF
48230	Landing or Log Deck	Repair Needed	8/31/21. PardueREAF Processed timber still in pile. Needs to be removed.
60111	Helispot	Unknown	
69884	Helispot	Unknown	
75665	Landing or Log Deck	Repair Needed	Standard repair