

# Suppression Repair Tiles



Cedar Creek  
OR-WF-20180  
10/23/2022 24 Hour  
127,283 acres as of 10/20/2022 @ 2027  
1:11,000,000  
Interior

- Accountable Property - Repair Status
- In Use - Fire Management (7)
  - Accountable Property
  - Other Property (4)
  - Range (1)
  - Water Tank (1)
  - In Use - Fire Management (21)
  - Repair Needed (62)
  - Completed - Ready for Inspection (1)
  - Completed - Inspected (17)
  - Other - See Comments (1)
  - Helispot (2)
  - Sling Site (4)
  - Value at Risk (3)
  - Water Development or Draft Site (3)
  - Structure Wrap (20)
  - Stream Crossing (7)
  - Road Repair (2)
  - Repair Point (22)
  - Landing or Log Deck (5)
  - Dozer Push (50)
  - Culvert (8)
  - Hazard (7)
  - Completed Dozer Line (36)
  - Completed Hand Line (46)
  - Completed Road as Line (11)
  - Access or Improved Road (10)
  - Repair Line (3)
  - In Use - Fire Management (12)
  - Needs Assessment (5)
  - Repair Needed (64)
  - In Progress (3)
  - Completed - Inspected (12)
  - Other - See Comments (9)
  - Confined
  - Uncolimated
  - Wildfire Daily Fire Perimeter
  - Interior Roads
  - Secondary Highway
  - Paved Roads
  - Dirt (Not Paved)
  - Paved Road
  - Crushed Road
  - Unimproved Road
  - Closed Roads
  - Wilderness
  - Roadless Area

**Note:** This map and associated tables have been filtered to only show Repair Points / Lines of Medium or High priority. There exists numerous other features of unknown or low priority repair needs throughout the fire area. The intended use of this map is to define/represent the repair work to be completed during IMT12 oversight of this incident. This map should **NOT** be considered a complete source for repair information.



# Interior



Repair ID	Priority	Point Type	Status	Repairs Needed	Repair Comments	Latitude	Longitude
4018	High	Culvert	Repair Needed	Clear culvert	4018 R 150, Culvert not match. Pull back depth and remove. Add Forest Road	43° 41' 49.79"	122° 13' 29.84"
4019	High	Culvert	Repair Needed	Clear culvert	4019 R 170, Culvert not match. Pull back depth and remove. Add Forest Road	43° 41' 51.74"	122° 13' 29.84"
4020	High	Door Hatch	Repair Needed	Full back	4020 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 41' 53.69"	122° 13' 29.84"
4021	High	Door Hatch	Repair Needed	Full back	4021 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 41' 55.64"	122° 13' 29.84"
4022	High	Door Hatch	Repair Needed	Full back	4022 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 41' 57.59"	122° 13' 29.84"
4023	High	Door Hatch	Repair Needed	Full back	4023 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 41' 59.54"	122° 13' 29.84"
4024	High	Door Hatch	Repair Needed	Full back	4024 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 01.49"	122° 13' 29.84"
4025	High	Door Hatch	Repair Needed	Full back	4025 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 03.44"	122° 13' 29.84"
4026	High	Door Hatch	Repair Needed	Full back	4026 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 05.39"	122° 13' 29.84"
4027	High	Door Hatch	Repair Needed	Full back	4027 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 07.34"	122° 13' 29.84"
4028	High	Door Hatch	Repair Needed	Full back	4028 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 09.29"	122° 13' 29.84"
4029	High	Door Hatch	Repair Needed	Full back	4029 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 11.24"	122° 13' 29.84"
4030	High	Door Hatch	Repair Needed	Full back	4030 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 13.19"	122° 13' 29.84"
4031	High	Door Hatch	Repair Needed	Full back	4031 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 15.14"	122° 13' 29.84"
4032	High	Door Hatch	Repair Needed	Full back	4032 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 17.09"	122° 13' 29.84"
4033	High	Door Hatch	Repair Needed	Full back	4033 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 19.04"	122° 13' 29.84"
4034	High	Door Hatch	Repair Needed	Full back	4034 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 20.99"	122° 13' 29.84"
4035	High	Door Hatch	Repair Needed	Full back	4035 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 22.94"	122° 13' 29.84"
4036	High	Door Hatch	Repair Needed	Full back	4036 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 24.89"	122° 13' 29.84"
4037	High	Door Hatch	Repair Needed	Full back	4037 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 26.84"	122° 13' 29.84"
4038	High	Door Hatch	Repair Needed	Full back	4038 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 28.79"	122° 13' 29.84"
4039	High	Door Hatch	Repair Needed	Full back	4039 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 30.74"	122° 13' 29.84"
4040	High	Door Hatch	Repair Needed	Full back	4040 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 32.69"	122° 13' 29.84"
4041	High	Door Hatch	Repair Needed	Full back	4041 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 34.64"	122° 13' 29.84"
4042	High	Door Hatch	Repair Needed	Full back	4042 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 36.59"	122° 13' 29.84"
4043	High	Door Hatch	Repair Needed	Full back	4043 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 38.54"	122° 13' 29.84"
4044	High	Door Hatch	Repair Needed	Full back	4044 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 40.49"	122° 13' 29.84"
4045	High	Door Hatch	Repair Needed	Full back	4045 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 42.44"	122° 13' 29.84"
4046	High	Door Hatch	Repair Needed	Full back	4046 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 44.39"	122° 13' 29.84"
4047	High	Door Hatch	Repair Needed	Full back	4047 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 46.34"	122° 13' 29.84"
4048	High	Door Hatch	Repair Needed	Full back	4048 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 48.29"	122° 13' 29.84"
4049	High	Door Hatch	Repair Needed	Full back	4049 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 50.24"	122° 13' 29.84"
4050	High	Door Hatch	Repair Needed	Full back	4050 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 52.19"	122° 13' 29.84"
4051	High	Door Hatch	Repair Needed	Full back	4051 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 54.14"	122° 13' 29.84"
4052	High	Door Hatch	Repair Needed	Full back	4052 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 56.09"	122° 13' 29.84"
4053	High	Door Hatch	Repair Needed	Full back	4053 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 42' 58.04"	122° 13' 29.84"
4054	High	Door Hatch	Repair Needed	Full back	4054 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 00.00"	122° 13' 29.84"
4055	High	Door Hatch	Repair Needed	Full back	4055 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 01.95"	122° 13' 29.84"
4056	High	Door Hatch	Repair Needed	Full back	4056 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 03.90"	122° 13' 29.84"
4057	High	Door Hatch	Repair Needed	Full back	4057 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 05.85"	122° 13' 29.84"
4058	High	Door Hatch	Repair Needed	Full back	4058 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 07.80"	122° 13' 29.84"
4059	High	Door Hatch	Repair Needed	Full back	4059 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 09.75"	122° 13' 29.84"
4060	High	Door Hatch	Repair Needed	Full back	4060 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 11.70"	122° 13' 29.84"
4061	High	Door Hatch	Repair Needed	Full back	4061 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 13.65"	122° 13' 29.84"
4062	High	Door Hatch	Repair Needed	Full back	4062 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 15.60"	122° 13' 29.84"
4063	High	Door Hatch	Repair Needed	Full back	4063 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 17.55"	122° 13' 29.84"
4064	High	Door Hatch	Repair Needed	Full back	4064 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 19.50"	122° 13' 29.84"
4065	High	Door Hatch	Repair Needed	Full back	4065 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 21.45"	122° 13' 29.84"
4066	High	Door Hatch	Repair Needed	Full back	4066 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 23.40"	122° 13' 29.84"
4067	High	Door Hatch	Repair Needed	Full back	4067 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 25.35"	122° 13' 29.84"
4068	High	Door Hatch	Repair Needed	Full back	4068 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 27.30"	122° 13' 29.84"
4069	High	Door Hatch	Repair Needed	Full back	4069 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 29.25"	122° 13' 29.84"
4070	High	Door Hatch	Repair Needed	Full back	4070 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 31.20"	122° 13' 29.84"
4071	High	Door Hatch	Repair Needed	Full back	4071 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 33.15"	122° 13' 29.84"
4072	High	Door Hatch	Repair Needed	Full back	4072 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 35.10"	122° 13' 29.84"
4073	High	Door Hatch	Repair Needed	Full back	4073 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 37.05"	122° 13' 29.84"
4074	High	Door Hatch	Repair Needed	Full back	4074 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 39.00"	122° 13' 29.84"
4075	High	Door Hatch	Repair Needed	Full back	4075 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 40.95"	122° 13' 29.84"
4076	High	Door Hatch	Repair Needed	Full back	4076 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 42.90"	122° 13' 29.84"
4077	High	Door Hatch	Repair Needed	Full back	4077 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 44.85"	122° 13' 29.84"
4078	High	Door Hatch	Repair Needed	Full back	4078 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 46.80"	122° 13' 29.84"
4079	High	Door Hatch	Repair Needed	Full back	4079 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 48.75"	122° 13' 29.84"
4080	High	Door Hatch	Repair Needed	Full back	4080 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 50.70"	122° 13' 29.84"
4081	High	Door Hatch	Repair Needed	Full back	4081 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 52.65"	122° 13' 29.84"
4082	High	Door Hatch	Repair Needed	Full back	4082 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 54.60"	122° 13' 29.84"
4083	High	Door Hatch	Repair Needed	Full back	4083 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 56.55"	122° 13' 29.84"
4084	High	Door Hatch	Repair Needed	Full back	4084 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 43' 58.50"	122° 13' 29.84"
4085	High	Door Hatch	Repair Needed	Full back	4085 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 00.45"	122° 13' 29.84"
4086	High	Door Hatch	Repair Needed	Full back	4086 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 02.40"	122° 13' 29.84"
4087	High	Door Hatch	Repair Needed	Full back	4087 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 04.35"	122° 13' 29.84"
4088	High	Door Hatch	Repair Needed	Full back	4088 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 06.30"	122° 13' 29.84"
4089	High	Door Hatch	Repair Needed	Full back	4089 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 08.25"	122° 13' 29.84"
4090	High	Door Hatch	Repair Needed	Full back	4090 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 10.20"	122° 13' 29.84"
4091	High	Door Hatch	Repair Needed	Full back	4091 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 12.15"	122° 13' 29.84"
4092	High	Door Hatch	Repair Needed	Full back	4092 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 14.10"	122° 13' 29.84"
4093	High	Door Hatch	Repair Needed	Full back	4093 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 16.05"	122° 13' 29.84"
4094	High	Door Hatch	Repair Needed	Full back	4094 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 18.00"	122° 13' 29.84"
4095	High	Door Hatch	Repair Needed	Full back	4095 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 20.00"	122° 13' 29.84"
4096	High	Door Hatch	Repair Needed	Full back	4096 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 22.00"	122° 13' 29.84"
4097	High	Door Hatch	Repair Needed	Full back	4097 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 24.00"	122° 13' 29.84"
4098	High	Door Hatch	Repair Needed	Full back	4098 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 26.00"	122° 13' 29.84"
4099	High	Door Hatch	Repair Needed	Full back	4099 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 28.00"	122° 13' 29.84"
4100	High	Door Hatch	Repair Needed	Full back	4100 R 150, Door hatch not match. Full back depth and remove. Add Forest Road	43° 44' 30.00"	122° 13' 29.84"