


Briefing Repair

11/24/2020

Cameron Peak CO-ARF-000636
208,913 acres from MMA Perimeter 11/06/2020 @ 1348



DIV D

DIV L

DIV T/U/V

PINGREE

DIV X/Y

East Troublesome Fire

Ownership	
	US Forest Service
	National Park Service
	Bureau of Land Management
	State
	Local Government
	Private
	Designated Wilderness

Repair Status Point	
	Completed - Inspected (27)
	Completed - Ready for Inspection (1)
	In Progress (5)
	Repair Needed (133)
	No Repair Needed (7)
	Unknown (46)

Repair Status Line	
	Completed - Inspected (180)
	Completed - Ready for Inspection (16)
	In Progress (17)
	Repair Needed (138)
	No Repair Needed (33)
	Other - See Comments (1)
	Unknown (7)

- Bridge (6)
- Camp (2)
- Clean Up Area (1)
- Culvert (3)
- Drop Point (25)
- Dozer Push (31)
- Fence - Cut/Damaged (10)
- Helibase (1)
- Unimproved Landing Area (1)
- Helispot (32)
- Landing or Log Deck (59)
- Repeater (7)
- Safety Zone (5)
- Staging Area (3)
- Water Source (11)
- Water Development or Draft Site (2)
- Division Break (4)

SA Gold
11/23/2020 1959
Datum: North American 1983