

Feature Category (Point Type)	Comments	Latitude WGS84 DDM	Longitude WGS84 DDM
Pump		33° 20.946' N	108° 04.794' W

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Aviation Route			Unknown	Not Cleared
Aviation Route			Unknown	Not Cleared
Completed Burnout	Hand ignitions		Unknown	Not Cleared
Completed Dozer Line		6/15: old road tank trapped @ road/gate and waterbarred. Needs seeding...	Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Very rocky unable to water bar.	Unknown	Not Cleared
Completed Dozer Line			Medium	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22, ARCH	Pull berm. Waterbar. Slash track hoe better tool. Reseed	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		North Star 4. Waterbar, pull berm. Reseed. Not much slash. Pull large material from green side to block access.	Unknown	Cleared for Operations
Completed Dozer Line	J.Ayers,06/15/22,ARC	6/15: seeded, tank trapped, water barred, smoothed berms	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Waterbar, cover w slash, knock down dozer berms, block access from campsite. Reestablish drainage near bottom	High	Cleared for Operations
Completed Dozer Line		Seeded. North Star 2. Will need machinery. Need to dis courage vehicle use post rehab 6/18: ripped, berms smoothed, tank trapped & blocked, slash placed in line	Unknown	Not Cleared
Completed Dozer Line		Repair will need equipment; steep so excavator w/thumb recommended		Cleared for Operations
Completed Dozer Line	Single blade along existing, then pioneers to tie into handline. Mod to heavy piles prepped for chipping	North Star 1	Medium	Cleared for Operations
Completed Dozer Line		seeded and slash placed	Unknown	Not Cleared
Completed Dozer Line	Up to 3 blades wide, ties into hand line. end of dozer line	Bloodgood 1. May need to reseed upper part where there is little slash	High	Not Cleared
Completed Dozer Line		Has been seeded; 6/19: berms smoothed access blocked with spread slash inside treeline	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Fairly float, line reseeded	Medium	Cleared for Mechanical Repair
Completed Dozer Line	Single blade dozerline, heavy piles of prepped line	McKnight 0. 6/19: berms are smoothed, handcrew has done waterbars	High	Not Cleared
Completed Dozer Line	Single track dozerline.	FSR 152A	High	Not Cleared
Completed Dozer Line	Single blade dozer, crosses blue line	FSR 152 B	High	Cleared for Operations
Completed Dozer Line		North Star 3. 6/18: berms knocked down, slash over line, entrance blocked, seeded	Unknown	Cleared for Operations
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	Very light scrape in meadow and used as road access	6/17: Seeding complete	Unknown	Not Cleared
Completed Dozer Line	needs material pulled onto line	seeding needed	Unknown	Not Cleared
Completed Dozer Line		Part of North Star 4	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/14/22, ARCH	6/19: waterbarred, slash scattered over line	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	Hand drawn based on READ Chamberlain	FSR 152 C	High	Not Cleared
Completed Hand Line		None needed	Unknown	Not Cleared
Completed Hand Line		6/15: handline obliterated	Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeded	Unknown	Not Cleared
Completed Hand Line	Improved existing trail		Unknown	Not Cleared
Completed Hand Line		6/19: pulled berms back, waterbarred, seeded, and slash over line	Unknown	Not Cleared

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Hand Line	Line for Wilson Lodge burnout. Plumbed		Unknown	Not Cleared
Completed Hand Line		Look for areas in the rocky section to get water off fire line. Do not stack large material.	Unknown	Not Cleared
Completed Hand Line			Medium	Not Cleared
Completed Hand Line	Plumbed handline from structure #6 to two track road 6/19: no longer plumbed	Seed, spread debris back over line	Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	handline off end of dozer line		Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeding complete	Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Road improved by single blade dozer. Light Brush cut and prepped for chipping		Unknown	Not Cleared
Completed Mixed Construction Line	Potential check line, single dozer line	6/19: tank trapped @ entrance, berms smoothed, slash covering line	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: chipping 3/4 complete, should be complete 6/20	Unknown	Not Cleared
Completed Road as Line	Delete section of this along 59 rd I forgot to stop streaming. 6/15: brushed and prepped for chipping.		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Old road used as line, no improvements made. Ties into handline		Unknown	Not Cleared
Completed Road as Line		6/19: graded	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: no improvements made, gate is shut	Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: No suppression improvements, no repair needed	Unknown	Not Cleared
Completed Road as Line		6/19: bladed where possible	Unknown	Not Cleared
Completed Road as Line		6/19: bladed completed where possible	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		Keep slash out of road. End of road is circle drive.	Unknown	Not Cleared
Completed Road as Line	Improved nonused road,		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing road 150	Existing road, no dozerline, grading recommended	Unknown	Not Cleared
Completed Road as Line	Checkline	6/19: Berms smoothed, cowboy gate closed (needs new stays), slash spread at entrance	Unknown	Not Cleared
Completed Road as Line		6/19: chipping and lop/spread underway. ;Approxima 5 1/2 miles of mostly continuous slash. Chipper inaccessible.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/18: graded	Unknown	Not Cleared
Completed Road as Line	Lopped and prepped for chipping		Unknown	Not Cleared
Completed Road as Line	graveled road. Prepped slash on east side. Prepped chipping piles on west side	6/19: chipper and hand crew working north along road spreading and chipping. crewwo	Unknown	Not Cleared
Other	If fire reaches this point consider bringing fire south from Apache peak trail / hand line South to the next viable check feature.		Unknown	Not Cleared
Planned Dozer Line		6/19: dozer line still does not exist at this time	Unknown	Not Cleared
Road Repair		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Not Cleared

Feature Category (Point Type)	Comments	Latitude WGS84 DDM	Longitude WGS84 DDM
Pump		33° 20.946' N	108° 04.794' W

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Aviation Route			Unknown	Not Cleared
Aviation Route			Unknown	Not Cleared
Completed Burnout	Hand ignitions		Unknown	Not Cleared
Completed Dozer Line		6/15: old road tank trapped @ road/gate and waterbarred. Needs seeding...	Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Very rocky unable to water bar.	Unknown	Not Cleared
Completed Dozer Line			Medium	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22, ARCH	Pull berm. Waterbar. Slash track hoe better tool. Reseed	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		North Star 4. Waterbar, pull berm. Reseed. Not much slash. Pull large material from green side to block access.	Unknown	Cleared for Operations
Completed Dozer Line	J.Ayers,06/15/22,ARC	6/15: seeded, tank trapped, water barred, smoothed berms	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Waterbar, cover w slash, knock down dozer berms, block access from campsite. Reestablish drainage near bottom	High	Cleared for Operations
Completed Dozer Line		Seeded. North Star 2. Will need machinery. Need to dis courage vehicle use post rehab 6/18: ripped, berms smoothed, tank trapped & blocked, slash placed in line	Unknown	Not Cleared
Completed Dozer Line		Repair will need equipment; steep so excavator w/thumb recommended		Cleared for Operations
Completed Dozer Line	Single blade along existing, then pioneers to tie into handline. Mod to heavy piles prepped for chipping	North Star 1	Medium	Cleared for Operations
Completed Dozer Line		seeded and slash placed	Unknown	Not Cleared
Completed Dozer Line	Up to 3 blades wide, ties into hand line. end of dozer line	Bloodgood 1. May need to reseed upper part where there is little slash	High	Not Cleared
Completed Dozer Line		Has been seeded; 6/19: berms smoothed access blocked with spread slash inside treeline	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Fairly float, line reseeded	Medium	Cleared for Mechanical Repair
Completed Dozer Line	Single blade dozerline, heavy piles of prepped line	McKnight 0. 6/19: berms are smoothed, handcrew has done waterbars	High	Not Cleared
Completed Dozer Line	Single track dozerline.	FSR 152A	High	Not Cleared
Completed Dozer Line	Single blade dozer, crosses blue line	FSR 152 B	High	Cleared for Operations
Completed Dozer Line		North Star 3. 6/18: berms knocked down, slash over line, entrance blocked, seeded	Unknown	Cleared for Operations
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	Very light scrape in meadow and used as road access	6/17: Seeding complete	Unknown	Not Cleared
Completed Dozer Line	needs material pulled onto line	seeding needed	Unknown	Not Cleared
Completed Dozer Line		Part of North Star 4	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/14/22, ARCH	6/19: waterbarred, slash scattered over line	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	Hand drawn based on READ Chamberlain	FSR 152 C	High	Not Cleared
Completed Hand Line		None needed	Unknown	Not Cleared
Completed Hand Line		6/15: handline obliterated	Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeded	Unknown	Not Cleared
Completed Hand Line	Improved existing trail		Unknown	Not Cleared
Completed Hand Line		6/19: pulled berms back, waterbarred, seeded, and slash over line	Unknown	Not Cleared

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Hand Line	Line for Wilson Lodge burnout. Plumbed		Unknown	Not Cleared
Completed Hand Line		Look for areas in the rocky section to get water off fire line. Do not stack large material.	Unknown	Not Cleared
Completed Hand Line			Medium	Not Cleared
Completed Hand Line	Plumbed handline from structure #6 to two track road 6/19: no longer plumbed	Seed, spread debris back over line	Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	handline off end of dozer line		Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeding complete	Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Road improved by single blade dozer. Light Brush cut and prepped for chipping		Unknown	Not Cleared
Completed Mixed Construction Line	Potential check line, single dozer line	6/19: tank trapped @ entrance, berms smoothed, slash covering line	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: chipping 3/4 complete, should be complete 6/20	Unknown	Not Cleared
Completed Road as Line	Delete section of this along 59 rd I forgot to stop streaming. 6/15: brushed and prepped for chipping.		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Old road used as line, no improvements made. Ties into handline		Unknown	Not Cleared
Completed Road as Line		6/19: graded	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: no improvements made, gate is shut	Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: No suppression improvements, no repair needed	Unknown	Not Cleared
Completed Road as Line		6/19: bladed where possible	Unknown	Not Cleared
Completed Road as Line		6/19: bladed completed where possible	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		Keep slash out of road. End of road is circle drive.	Unknown	Not Cleared
Completed Road as Line	Improved nonused road,		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing road 150	Existing road, no dozerline, grading recommended	Unknown	Not Cleared
Completed Road as Line	Checkline	6/19: Berms smoothed, cowboy gate closed (needs new stays), slash spread at entrance	Unknown	Not Cleared
Completed Road as Line		6/19: chipping and lop/spread underway. ;Approxima 5 1/2 miles of mostly continuous slash. Chipper inaccessible.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/18: graded	Unknown	Not Cleared
Completed Road as Line	Lopped and prepped for chipping		Unknown	Not Cleared
Completed Road as Line	graveled road. Prepped slash on east side. Prepped chipping piles on west side	6/19: chipper and hand crew working north along road spreading and chipping. crewwo	Unknown	Not Cleared
Other	If fire reaches this point consider bringing fire south from Apache peak trail / hand line South to the next viable check feature.		Unknown	Not Cleared
Planned Dozer Line		6/19: dozer line still does not exist at this time	Unknown	Not Cleared
Road Repair		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Not Cleared