



SWEDES INCIDENT

CA-BTU-010969

DAMAGE INSPECTION



AUGUST 16-22, 2013

CAL FIRE INCIDENT MANAGEMENT TEAM 1

TABLE OF CONTENTS

TAB# 1 NARRATIVE

TAB# 2 DAMAGE INSPECTION FORMS

TAB# 3 DAMAGE INSPECTION PICTURES

TAB# 4 MAP

STAFF:

Phillip Fligiel	PSC1	LA City Fire
Frank Reilly	DINS	CAL FIRE
Dave Krussow	FOBS	CAL FIRE
Dave Rogers	FOBS	Vacaville Fire

SWEDES INCIDENT

CA-BTU-010969

BUTTE COUNTY

DAMAGE INSPECTION NARRATIVE

On August 16, 2013 at approximately 1630 hrs **CAL FIRE**/Butte County Fire with several other agencies responded to a reported vegetation fire on Swedes Flats Road east of Oro-Bangor Hwy. The fire moved in the direction of improved properties and structure defense was put in place. A total of 7 properties were destroyed during the initial attack phase of the fire. The fire made significant runs and threatened over 400 other homes and the distribution lines for PG&E. Due to direct suppression efforts no additional properties or infrastructure was affected.



Organization: CALFIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION
Event Type: [X] Fire [] Flood [] Wind [] Earthquake [] Other:
Incident Name: Swedes Incident Number: CABTU 010969
Incident Start Date: 08/16/13 Recording Date: 08/19/13 Time Recorded: 1800
First Name: David Last Name: Krussow Contact Phone: 530-889-0111 Contact Email: David.Krussow@fire.ca Camera Name: GPS Name:
2 SITE INFORMATION
Street No: Ukn Street Pre-Direction: Street Name: Quality Street Type: Rd. Unit Number:
City: Oroville State: CA Zip: 95966 -
Access to Site: [X] Walked Built Property [] Walked Built Property Spoke with Homeowner & Accessed Interior [] Spoke with Homeowner about Damage & Street Access [] Street Access Only [] Aerial Assessment [] Historical Records
GPS Position: Latitude: 39, 27.8700 Longitude: -121, 23.8190 Way Point Number: 27
3 PRIMARY STRUCTURE DAMAGE INFORMATION
Structure Category: [X] Residential [] Business/Non-Profit/Government
Structure Type: [] Fixed [X] RV/Travel Trailer [] Mobile Structure (e.g. Mobile Home)
Extent of Damage: [X] Destroyed [] Damaged [] No Damage [] N/D
4 OTHER INFORMATION
List Hazards Preventing Safe Building/Property Re-Entry:
List Other Damage Not Documented Above: 2 other trailers, 2 outbuildings destroyed
List Other Pertinent Comments:



Organization: CAL FIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION
Event Type: [X] Fire [] Flood [] Wind [] Earthquake [] Other:
Incident Name: SWEDES Incident Number: CABTU010969
Incident Start Date: 08/16/13 Recording Date: 08/19/13 Time Recorded: 1800
First Name: David Last Name: Krussow Contact Phone: 530-889-0111 Contact Email: david.krussow@fire.ca Camera Name: GPS Name:

2 SITE INFORMATION
Street No: UKN Street Pre-Direction: Street Name: DEER VALLEY Street Type: RD. Unit Number:
City: OROVILLE State: CA Zip: 95966 -
Access to Site: [X] Walked Built Property [] Walked Built Property Spoke with Homeowner & Accessed Interior [] Spoke with Homeowner about Damage & Street Access [] Street Access Only [] Aerial Assessment [] Historical Records
GPS Position: Latitude: 39, 27.4960 Longitude: -121, 23.7780 Way Point Number: 29

3 PRIMARY STRUCTURE DAMAGE INFORMATION
Structure Category: [] Residential [] Business/Non-Profit/Government
Structure Type: [] Fixed [X] RV/Travel Trailer [] Mobile Structure (e.g. Mobile Home)
Extent of Damage: [X] Destroyed [] Damaged [] No Damage [] N/D

4 OTHER INFORMATION
List Hazards Preventing Safe Building/Property Re-Entry:
List Other Damage Not Documented Above:
List Other Pertinent Comments: UNKNOWN IF OCCUPIED



Organization: CAL FIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION Final 2013

1	INCIDENT & FIELD DATA COLLECTOR INFORMATION								
	Event Type:		<input checked="" type="checkbox"/> Fire	<input type="checkbox"/> Flood	<input type="checkbox"/> Wind	<input type="checkbox"/> Earthquake	<input type="checkbox"/> Other:		
	Incident Name: SWEDES			Incident Number: CABTU010969					
	Incident Start Date: 08/16/13			Recording Date: 08/19/13		Time Recorded: 1800			
	First Name: David		Last Name: Krussow		Contact Phone: 530-889-0111	Contact Email: david.krussow@fire.ca.	Camera Name:	GPS Name:	
2	SITE INFORMATION					Image Number(s):			
	Street No: UKN	Street Pre-Direction: (e.g. North, South, etc.)		Street Name: DEER VALLEY		Street Type: RD. (e.g. RD, ST, etc.)	Unit Number:		
	City: OROVILLE			State: CA		Zip: 95966 -			
	Access to Site: (Check All That Apply)	<input checked="" type="checkbox"/> Walked Built Property	<input type="checkbox"/> Walked Built Property Spoke with Homeowner & Accessed Interior		<input type="checkbox"/> Spoke with Homeowner about Damage & Street Access		<input type="checkbox"/> Street Access Only	<input type="checkbox"/> Aerial Assessment	<input type="checkbox"/> Historical Records
	GPS Position:	Latitude (Degrees Decimal Minutes): 39, 27.4960		Longitude (Degrees Decimal Minutes): -121, 23.7780		Way Point Number: 29A			
3	PRIMARY STRUCTURE DAMAGE INFORMATION					Image Number(s): 2354-2356			
	Structure Category:		<input type="checkbox"/> Residential		<input type="checkbox"/> Business/Non-Profit/Government				
	Structure Type:		<input type="checkbox"/> Fixed	<input checked="" type="checkbox"/> RV/Travel Trailer		<input type="checkbox"/> Mobile Structure (e.g. Mobile Home)			
Extent of Damage:		<input checked="" type="checkbox"/> Destroyed	<input type="checkbox"/> Damaged		<input type="checkbox"/> No Damage	<input type="checkbox"/> N/D			
4	OTHER INFORMATION					Image Number(s):			
	List Hazards Preventing Safe Building/Property Re-Entry:								
	List Other Damage Not Documented Above:								
	List Other Pertinent Comments: UNKNOWN IF OCCUPIED/ON SAME PROPERTY AS WP29								



Organization: CAL FIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION

Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION						
Event Type:	<input checked="" type="checkbox"/> Fire	<input type="checkbox"/> Flood	<input type="checkbox"/> Wind	<input type="checkbox"/> Earthquake	<input type="checkbox"/> Other:	
Incident Name: SWEDES			Incident Number: CABTU010969			
Incident Start Date: 08/16/13			Recording Date: 08/19/13		Time Recorded: 1800	
First Name:	Last Name:	Contact Phone:	Contact Email:	Camera Name:	GPS Name:	
David	Krussow	530-889-0111	david.krussow@fire.ca.			
2 SITE INFORMATION					Image Number(s):	
Street No:	Street Pre-Direction:	Street Name:	Street Type:	Unit Number:		
UKN	(e.g. North, South, etc.)	GORMAN RANCH	(e.g. RD, ST, etc.)			
City: OROVILLE			State: CA	Zip: 95966 -		
Access to Site: (Check All That Apply)	<input checked="" type="checkbox"/> Walked Built Property	<input type="checkbox"/> Walked Built Property Spoke with Homeowner & Accessed Interior	<input type="checkbox"/> Spoke with Homeowner about Damage & Street Access	<input type="checkbox"/> Street Access Only	<input type="checkbox"/> Aerial Assessment	<input type="checkbox"/> Historical Records
GPS Position:	Latitude (Degrees Decimal Minutes) 39, 27.2050		Longitude (Degrees Decimal Minutes) -121, 24.8460		Way Point Number: 34	
3 PRIMARY STRUCTURE DAMAGE INFORMATION					Image Number(s): 2354-2356	
Structure Category:		<input type="checkbox"/> Residential	<input type="checkbox"/> Business/Non-Profit/Government			
Structure Type:	<input type="checkbox"/> Fixed	<input checked="" type="checkbox"/> RV/Travel Trailer	<input type="checkbox"/> Mobile Structure (e.g. Mobile Home)			
Extent of Damage:	<input checked="" type="checkbox"/> Destroyed	<input type="checkbox"/> Damaged	<input type="checkbox"/> No Damage	<input type="checkbox"/> N/D		
4 OTHER INFORMATION					Image Number(s):	
List Hazards Preventing Safe Building/Property Re-Entry:						
List Other Damage Not Documented Above:						
List Other Pertinent Comments: UNKNOWN IF OCCUPIED						



Organization: CAL FIRE

Department: CABTU



RAPID DAMAGE INSPECTION Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION									
Event Type:		<input checked="" type="checkbox"/> Fire	<input type="checkbox"/> Flood	<input type="checkbox"/> Wind	<input type="checkbox"/> Earthquake	<input type="checkbox"/> Other:			
Incident Name: SWEDES				Incident Number: CABTU010969					
Incident Start Date: 08/16/13				Recording Date: 08/19/13			Time Recorded: 1800		
First Name: David		Last Name: Krussow		Contact Phone: 530-889-0111		Contact Email: david.krussow@fire.ca.		Camera Name:	GPS Name:
2 SITE INFORMATION									
Street No: UKN		Street Pre-Direction: (e.g. North, South, etc.)		Street Name: GORMAN RANCH			Street Type: (e.g. RD, ST, etc.)		Unit Number:
City: OROVILLE				State: CA			Zip: 95966 -		
Access to Site: (Check All That Apply)	<input checked="" type="checkbox"/> Walked Built Property	<input type="checkbox"/> Walked Built Property Spoke with Homeowner & Accessed Interior			<input type="checkbox"/> Spoke with Homeowner about Damage & Street Access		<input type="checkbox"/> Street Access Only	<input type="checkbox"/> Aerial Assessment	<input type="checkbox"/> Historical Records
GPS Position:	Latitude (Degrees Decimal Minutes) 39, 27.1820			Longitude (Degrees Decimal Minutes) -121, 24.6620			Way Point Number: 35		
3 PRIMARY STRUCTURE DAMAGE INFORMATION								Image Number(s): 2354-2356	
Structure Category:			<input type="checkbox"/> Residential			<input type="checkbox"/> Business/Non-Profit/Government			
Structure Type:		<input type="checkbox"/> Fixed		<input checked="" type="checkbox"/> RV/Travel Trailer		<input type="checkbox"/> Mobile Structure (e.g. Mobile Home)			
Extent of Damage:		<input checked="" type="checkbox"/> Destroyed		<input type="checkbox"/> Damaged		<input type="checkbox"/> No Damage		<input type="checkbox"/> N/D	
4 OTHER INFORMATION									
Image Number(s):									
List Hazards Preventing Safe Building/Property Re-Entry:									
List Other Damage Not Documented Above:									
List Other Pertinent Comments: UNKNOWN IF OCCUPIED									



Organization: CAL FIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION						
Event Type:	<input checked="" type="checkbox"/> Fire	<input type="checkbox"/> Flood	<input type="checkbox"/> Wind	<input type="checkbox"/> Earthquake	<input type="checkbox"/> Other:	
Incident Name: SWEDES			Incident Number: CABTU010969			
Incident Start Date: 08/16/13			Recording Date: 08/19/13		Time Recorded: 1800	
First Name: David	Last Name: Krussow	Contact Phone: 530-889-0111	Contact Email: david.krussow@fire.ca.	Camera Name:	GPS Name:	
2 SITE INFORMATION				Image Number(s):		
Street No: UKN	Street Pre-Direction: (e.g. North, South, etc.)	Street Name: GORMAN RANCH		Street Type: (e.g. RD, ST, etc.)	Unit Number:	
City: OROVILLE			State: CA		Zip: 95966 -	
Access to Site: (Check All That Apply)	<input checked="" type="checkbox"/> Walked Built Property	<input type="checkbox"/> Walked Built Property Spoke with Homeowner & Accessed Interior	<input type="checkbox"/> Spoke with Homeowner about Damage & Street Access	<input type="checkbox"/> Street Access Only	<input type="checkbox"/> Aerial Assessment	<input type="checkbox"/> Historical Records
GPS Position:	Latitude (Degrees Decimal Minutes): 39, 27.2070	Longitude (Degrees Decimal Minutes): -121, 24.6840		Way Point Number: 36		
3 PRIMARY STRUCTURE DAMAGE INFORMATION				Image Number(s): 2354-2356		
Structure Category:		<input type="checkbox"/> Residential		<input type="checkbox"/> Business/Non-Profit/Government		
Structure Type:		<input type="checkbox"/> Fixed		<input checked="" type="checkbox"/> RV/Travel Trailer		<input type="checkbox"/> Mobile Structure (e.g. Mobile Home)
Extent of Damage:		<input checked="" type="checkbox"/> Destroyed		<input type="checkbox"/> Damaged		<input type="checkbox"/> No Damage
						<input type="checkbox"/> N/D
4 OTHER INFORMATION				Image Number(s):		
List Hazards Preventing Safe Building/Property Re-Entry:						
List Other Damage Not Documented Above:						
List Other Pertinent Comments: UNKNOWN IF OCCUPIED						



Organization: CAL FIRE

Department: CABTU



NIST National Institute of Standards and Technology

RAPID DAMAGE INSPECTION Final 2013

1 INCIDENT & FIELD DATA COLLECTOR INFORMATION
Event Type: [X] Fire [] Flood [] Wind [] Earthquake [] Other:
Incident Name: SWEDES Incident Number: CABTU010969
Incident Start Date: 08/16/13 Recording Date: 08/19/13 Time Recorded: 1800
First Name: David Last Name: Krussow Contact Phone: 530-889-0111 Contact Email: david.krussow@fire.ca Camera Name: GPS Name:

2 SITE INFORMATION
Street No: UKN Street Pre-Direction: Street Name: GORMAN RANCH Street Type: Unit Number:
City: OROVILLE State: CA Zip: 95966 -
Access to Site: [X] Walked Built Property [] Walked Built Property Spoke with Homeowner & Accessed Interior [] Spoke with Homeowner about Damage & Street Access [] Street Access Only [] Aerial Assessment [] Historical Records
GPS Position: Latitude: 39, 26.9620 Longitude: -121, 24.6540 Way Point Number: 37

3 PRIMARY STRUCTURE DAMAGE INFORMATION
Structure Category: [] Residential [] Business/Non-Profit/Government
Structure Type: [] Fixed [X] RV/Travel Trailer [] Mobile Structure (e.g. Mobile Home)
Extent of Damage: [X] Destroyed [] Damaged [] No Damage [] N/D

4 OTHER INFORMATION
List Hazards Preventing Safe Building/Property Re-Entry:
List Other Damage Not Documented Above:
List Other Pertinent Comments: UNKNOWN IF OCCUPIED















SWEDES INCIDENT - CA-BTU-010969
AUG 20, 2013



DAMAGE INSPECTION MAP

