




Spillway DWR
17-CA-CDF-000114
02/20/2017
0600 - 0600
NAD83

- Monitor_Camera_Locations
- Monitor_Path_Locations
- Monitor_Path_FCO_Bridge_Deck
- Monitor_Path_FCO_Rovers_Spillway_Emb
- Monitor_Path_Thermalito_Diversion_Dam
- Monitor_MCOM_Trailer
- Monitor_Path_ORO_Road
- ICP
- Drop Point
- Power Lines
- Emergency Flow Path
- Construction Area
- Emergency Spillway
- Division Boundaries
- Sensitive Resource Areas

0 0.25 0.5 Miles

IMT 3 GIS
 February 19, 2017
 1730 Hours



-Monitor Camera
 -Monitor Path Location
 -Monitor Path FCO Bridge Deck
 -Monitor MCOM Trailer
 -Monitor Path FCO Rovers Left & Right Spillway Embankment

-Monitor Path Location
 -Monitor Path Thermalito Diversion Dam

-Monitor Camera
 -Monitor Path Location
 -Monitor Path ORO Road