



Suppression Repair GRAY = COMPLETED

- | | | | |
|----------------------------------|--------------------------|--|---------------------------------|
| Suppression Repair Points | | Suppression Repair Status Masking | |
| Bridge | Lop and Scatter Trees | GPS Verified - No Assessment | Completed - Needs READ Approval |
| Cattleguard Damage | Meadow Damage | Not GPS Verified - No Assessment | Completed - Approved |
| Chipping Slash | Other | Repair Needed | |
| Culvert Damage | Retardant Avoidance Area | Completed - Needs READ Approval | |
| Dozer Push | Retardant Track Point | Completed - Approved | |
| Drop Point | Road Needs Repair | | |
| Equipment Found | Safety Zone | | |
| Fence Damage | Staging Area | | |
| Gate | Water Course Crossing | | |
| Hand Line Repair | Water Drafting Location | | |
| Hazard Tree | Waterbar Needed | | |
| Helispot | | | |

Suppression Repair

Mendocino Complex Ranch Fire - Div. Q
CA-MEU-008674
8/22/2018

— Contained Fire Edge	— Branch Break	● Helispot
— Completed Dozer Line	— Division Break	● Dip Site
— Completed Hand Line	— Incident Command Post	● Mobile Retardant Base
— Road as Completed Line	— Camp	● Water Source
● Active Mines (2010)	— Staging Area	● Repeater
— Direct Protection Areas	● Drop Point	● Mobile Weather Unit



Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. Q
August 22, 2018

- Ownership**
- Local Government
 - Other State Lands
 - USDA Forest Service
 - Bureau of Land Management
 - Bureau of Indian Affairs

QR Code

NAD83 UTM Zone 10
Contour Interval: 40 ft.
Produced: 8/22/2018 12:56:20 AM

0 0.25 0.5 0.75 Miles

Suppression Repair

Mendocino Complex Ranch Fire - Div. Q
CA-MEU-008674
8/22/2018