



Suppression Repair
 Gray = Completed

Suppression Repair Lines

- GPS Verified - No Assessment
- Not GPS Verified - No Assessment
- Repair Needed
- Completed - Needs READ Approval
- Completed - Approved

Suppression Repair
 Mendocino Complex Ranch Fire
 Retardant Location
 CA-MEU-008674
 8/25/2018

	Uncontrolled Fire Edge		Drop Point
	Contained Fire Edge		Helispot
	Completed Dozer Line		Dip Site
	Completed Hand Line		Mobile Retardant Base
	Road as Completed Line		Water Source
	Proposed Dozer Line		Repeater
	Planned Fire Line		Mobile Weather Unit
	ZoneBreakLines		

Mendocino Complex
 CA-MEU-008674
 Suppression Repair
 Retardant Locations
 August 25, 2018

Retardant

Ownership

- Other State Lands
- USDA Forest Service
- Bureau of Land Management
- Bureau of Indian Affairs

Other Symbols:

- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area

NAD83 UTM Zone 10
 Contour Interval: 200ft.
 Produced: 8/24/2018 11:12:10 PM

0 0.25 0.5 1 Miles
 1:30,000

Suppression Repair
 Mendocino Complex Ranch Fire
 Retardant Locations
 CA-MEU-008674
 8/25/2018