



Suppression Repair
 Gray = Completed

Suppression Repair Lines

- GPS Verified - No Assessment
- Not GPS Verified - No Assessment
- Repair Needed
- Completed - Needs READ Approval
- Completed - Approved

Suppression Repair
 Mendocino Complex Div D/E
 Ranch Fire Overview
 CA-MEU-008674
 8/31/2018



Mendocino Complex Div - D/E
CA-MEU-008674
Suppression Repair
Ranch Fire Overview
August 31, 2018

- Ownership**
- Other State Lands
 - USDA Forest Service
- Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Direct Protection Areas
 - Wilderness Area
- Branch Break
 - Division Break
 - Incident Command Post
 - Camp
 - Staging Area
 - Drop Point
 - Helispot
 - Dip Site
 - Water Source
 - Repeater
 - Mobile Weather Unit
 - Bridge (w/ weight limit)
- NAD83 UTM Zone 10**
 Contour Interval: 100 ft.
 Produced: 8/31/2018 12:45:57 AM
- 1:15,000

Suppression Repair
 Mendocino Complex Div D/E
 Ranch Fire Overview
 CA-MEU-008674
 8/31/2018