



- Suppression Repair**
Gray = Completed
- Suppression Repair Points**
- Handwritten Repair Status
 - Bridge Repair Needed
 - Chipping Blush Repair Needed
 - Chipping Blush Completed - Approved
 - Clearcut Damage Repair Needed
 - Clearcut Damage Completed - Approved
 - Clearcut Patch Repair Needed
 - Clearcut Patch Completed - Approved
 - Drip Point Repair Needed
 - Equipment Fuel Repair Needed
 - Fence Damage Repair Needed
 - Fence Damage Completed - Approved
 - Fuel Repair Needed
 - Gate Completed - Approved
 - Hazard Tree Repair Needed
 - Handicap Repair Needed
 - Log and Scatter Trees Repair Needed
 - Meadow Damage Repair Needed
 - Other - Club
 - Other Repair Needed
 - Other Completed - Approved
 - Rebarbed Track Point Repair Needed
 - Road Needs Repair Repair Needed
 - Road Needs Repair Completed - Approved
 - Water Course Crossing Repair Needed
 - Water Course Crossing Completed - Approved
 - Water Drafting Location Repair Needed
 - Water Needed Repair Needed
 - Water Needed Completed - Approved
- Suppression Repair Lines**
- GPS Verified - No Assessment
 - Not GPS Verified - No Assessment
 - Paper Needed
 - Completed - Needs READ Approval
 - Completed - Approved

Suppression Repair

Div D/E
Mendocino Complex
CA-MEU-008674
September 3, 2018

Produced 9/14/18 PM 9/2/2018
1:15,000
NAD83 UTM Zone 10N



Suppression Repair - Div D/E
Mendocino Complex
CA-MEU-008674
September 3, 2018

Road Class shown in fuschia
Not all roads show Road Class values

- Contained Fire Edge
- XXXXX Completed Dozer Line
- H-H-H Completed Hand Line
- R-R-R Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Ownership**
- Other State Lands
- USDA Forest Service

Suppression Repair

Div D/E
Mendocino Complex
CA-MEU-008674
September 3, 2018