



- Suppression Repair Gray = Completed**
- Suppression Repair Points**
- Handwritten Repair Status
 - Chipping Station, Repair Needed
 - Chipping Station, Completed - Approved
 - Clearcut Damage, Repair Needed
 - Clearcut Damage, Completed - Approved
 - Door Push, Repair Needed
 - Door Push, Completed - Approved
 - Drip Flare, Repair Needed
 - Equipment Failure, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Completed - Approved
 - Handicap, Repair Needed
 - Loose and Scatter Trees, Repair Needed
 - Meadow Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Other, Paper Repair Needed
 - Other, Paper Completed - Approved
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Closing, Repair Needed
 - Water Course Closing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Waterbar Needed, Repair Needed
 - Waterbar Needed, Completed - Approved
- Suppression Repair Lines**
- Repair Status
 - GPS Verified - No Assessment
 - Not GPS Verified - No Assessment
 - Paper Repair Needed
 - Completed - Needs READ Approval
 - Completed - Approved

Suppression Repair

Div F/G

Mendocino Complex

CA-MEU-008674

September 3, 2018

Produced: 9/19/2018 10:59 PM
9/2/2018

NAD83 UTM Zone 10N



Suppression Repair - Div F/G

Mendocino Complex

CA-MEU-008674

September 3, 2018

Road Class shown in fuchsia

Not all roads show Road Class values

- Bridge (w/ weight limit)
- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Ownership
- USDA Forest Service

Suppression Repair

Div F/G

Mendocino Complex

CA-MEU-008674

September 3, 2018