

Branch I

Branch II

Branch III

Suppression Repair
Gray = Completed

Repair_Status

- GPS Verified - No Assessment
- Not GPS Verified - No Assessment
- Repair Needed
- Completed - Needs READ Approval
- Completed - Approved

Operations & Suppression Repair

Mendocino Complex Ranch Fire Overview
CA-MEU-008674
September 03 2018

	Uncontrolled Fire Edge		Branch Break		Drop Point
	Contained Fire Edge		Division Break		Helispot
	Completed Dozer Line		Incident Command Post		Dip Site
	Completed Hand Line		Water Source		Repeater
	Road as Completed Line		Camp		Mobile Weather Unit
	Staging Area		Pump		

Mendocino Complex
CA-MEU-008674
Ranch Fire Operations & Suppression Repair
September 3, 2018

Ownership

	Local Government		Bureau of Reclamation		Bridge (w/ weight limit)
	CA Dept. of Parks and Recreation		Bureau of Land Management		County Boundary
	CA Dept. of Fish and Wildlife		Bureau of Indian Affairs		Equipment Avoidance Areas
	Other State Lands		Department of Defense		Direct Protection Areas
	USDA Forest Service		Other Federal Lands		Wilderness Area
					Rehab Avoidance Area

NAD83 UTM Zone 10
Contour Interval: 200 ft.
 Produced: 9/2/2018 9:49:47 PM

0 0.5 1 2 Miles
 1:73,000

Operations & Suppression Repair

Mendocino Complex Ranch Fire Overview
CA-MEU-008674
September 03 2018

