



- Suppression Repair Gray = Completed**
- Suppression Repair Points**
- Point Type: Repair Needed
 - Chipping Station: Repair Needed
 - Chipping Station: Completed - Approved
 - Cable Cut: Repair Needed
 - Cable Cut: Completed - Approved
 - Clear Path: Repair Needed
 - Clear Path: Completed - Approved
 - Drop Point: Repair Needed
 - Equipment Point: Repair Needed
 - Force Damage: Repair Needed
 - Force Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Handout: Repair Needed
 - Lo and Scatter Trees: Repair Needed
 - Maintain Damage: Repair Needed
 - Other: Repair Needed
 - Other: Completed - Approved
 - Repaired Track Point: Repair Needed
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Drilling Location: Repair Needed
 - Waterline: Repair Needed
 - Waterline: Completed - Approved
- Suppression Repair Lines**
- Point Status: No Assessment
 - Not GPS Verified: No Assessment
 - Repair Needed
 - Completed: Needs ROAD Approval
 - Completed: Approved

Suppression Repair

Div B/C
Mendocino Complex
CA-MEU-008674
September 4, 2018



Suppression Repair - Div B/C
Mendocino Complex
CA-MEU-008674
September 4, 2018

Road Class shown in fuchsia
 Not all roads show Road Class values

- Bridge (w/ weight limit)
- Active Mines (2010)
- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Ownership
- Other State Lands
- USDA Forest Service

Suppression Repair

Div B/C
Mendocino Complex
CA-MEU-008674
September 4, 2018