


- Suppression Repair**  
 Gray = Completed
- Suppression Repair Points**
- PointType Repair Status
- ▲ Road Repair Needed
  - ▲ Clearing Slash Repair Needed
  - ▲ Clearing Slash Completed - Approved
  - ▲ Culvert Damage Repair Needed
  - ▲ Culvert Damage Completed - Approved
  - ▲ Down Pile Repair Needed
  - ▲ Down Pile Completed - Approved
  - ▲ Drop Point Repair Needed
  - ▲ Equipment Failure Repair Needed
  - ▲ Fence Damage Repair Needed
  - ▲ Fence Damage Completed - Approved
  - ▲ Gate Repair Needed
  - ▲ Gate Completed - Approved
  - ▲ Hazard Tree Repair Needed
  - ▲ Hazard Tree Repair Completed - Approved
  - ▲ Lockup Repair Needed
  - ▲ Log and Snufflers Repair Needed
  - ▲ Meadow Damage Repair Needed
  - ▲ Other Repair Needed
  - ▲ Other Repair Completed - Approved
  - ▲ Resident Truck Point Repair Needed
  - ▲ Road Needs Repair Repair Needed
  - ▲ Road Needs Repair Completed - Approved
  - ▲ Water Course Crossing Repair Needed
  - ▲ Water Course Crossing Completed - Approved
  - ▲ Water Drafting Location Repair Needed
  - ▲ Waterhead Repair Needed
  - ▲ Waterhead Completed - Approved
- Suppression Repair Lines**
- Point Status
- GPS Verified - No Assessment
  - Not GPS Verified - No Assessment
  - Repair Needed
  - Completed - Needs ROAD Approval
  - Completed - Approved

**Suppression Repair**  
 Div D/E  
 Mendocino Complex  
 CA-MEU-008674  
 September 5, 2018



**Suppression Repair - Div D/E**  
**Mendocino Complex**  
**CA-MEU-008674**  
**September 5, 2018**

- Road Class shown in fuschia  
 Not all roads show Road Class values
- Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Bridge (w/ weight limit)
  - Direct Protection Areas
  - Wilderness Area
  - Ownership**
  - Other State Lands
  - USDA Forest Service

**Suppression Repair**  
 Div D/E  
 Mendocino Complex  
 CA-MEU-008674  
 September 5, 2018