



- Suppression Repair**  
Gray = Completed
- PointType: Repair Status**
- Bridge Repair Needed
  - Clearing Slash Repair Needed
  - Clearing Slash Completed - Approved
  - Culvert Damage Repair Needed
  - Culvert Damage Completed - Approved
  - Clear Path Repair Needed
  - Clear Path Completed - Approved
  - Drop Point Repair Needed
  - Equipment Fault Repair Needed
  - Fences Damage Repair Needed
  - Fences Damage Completed - Approved
  - Gate Repair Needed
  - Gate Completed - Approved
  - Hazard Tree Repair Needed
  - Helipad Repair Needed
  - Log and Butler Trees Repair Needed
  - Meadow Damage Repair Needed
  - Other Repair Needed
  - Other Completed - Approved
  - Roadwork Track Point Repair Needed
  - Roadwork Track Point Completed - Approved
  - Water Course Crossing - Old
  - Water Course Crossing Repair Needed
  - Water Course Crossing Completed - Approved
  - Water Drilling Location Repair Needed
  - Water Needed Repair Needed
  - Water Needed Completed - Approved
- Suppression Repair Lines**
- Repair Status
- GPS Verified - No Assessment
  - Not GPS Verified - No Assessment
  - Repair Needed
  - Completed - Needs READ Approval
  - Completed - Approved

**Suppression Repair**  
Div F/G  
Mendocino Complex  
CA-MEU-008674  
September 5, 2018

Produced: 10/15/15 10:11 AM 9/4/2018  
1:15,000  
NAD83 UTM Zone 10N



**Suppression Repair - Div F/G**  
**Mendocino Complex**  
**CA-MEU-008674**  
**September 5, 2018**

Road Class shown in fuschia  
Not all roads show Road Class values

- Contained Fire Edge
- Completed Dozer Line
- Direct Protection Areas
- Wilderness Area
- Ownership
- USDA Forest Service
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)

**Suppression Repair**  
Div F/G  
Mendocino Complex  
CA-MEU-008674  
September 5, 2018