



- Suppression Repair Points**
- Point Type, Repair Status
 - Bridge Repair Needed
 - Chipping Blank Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Flush Repair Needed
 - Clear Flush, Completed - Approved
 - Drop Point Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Frame Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree Repair Needed
 - Hazard Tree, Repair Needed
 - Lip and Scatter Trees, Repair Needed
 - Miscellaneous Damage, Repair Needed
 - Other Repair Needed
 - Other, Completed - Approved
 - Retention Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Needs Repair, Repair Needed
 - Water Needs Repair, Completed - Approved

Road Class shown
25 in fuschia. Not all
roads show Road
Class values

SUPPRESSION REPAIR, 09/07/18
Div B/C

SoCal IMT 3 GIS
September 06, 2018
1831

Datum: NAD 83

QR Code



Mendocino Complex
CA-MEU-008674
September 7, 2018
SUPPRESSION REPAIR
Div B/C

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Other State Lands
- USDA Forest Service

— Contained Fire Edge
--- Completed Dozer Line
H-H-H Completed Hand Line
R-R-R Road as Completed Line

□ Bridge (w/ weight limit)
○ Active Mines (2010)

⊞ Direct Protection Areas