



Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex CA-MEU-008674 September 7, 2018 SUPPRESSION REPAIR Div D/E

- ### Repair Legend
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area

- ### Ownership
- Other State Lands
 - USDA Forest Service

SUPPRESSION REPAIR, 09/07/18
Div D/E

SoCal IMT 3 GIS
September 06, 2018
1835

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83

SOUTHERN CALIFORNIA
FIRE AUTHORITY

FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE

INTERAGENCY INCIDENT MANAGEMENT